



DueList Report

AW109SP GRAND NEW

S/N 22294 VH-LCF

OWNER: WALKER AIR SERVICES PTY
LIMITEDOPERATOR: WALKER AIR SERVICES PTY
LIMITEDCAMO: LEONARDO COMPANY SPA-
AIRCRAFT DIVISIONADDRESS: LEVEL 50, 1 FARRER PLACE
SYDNEY NSW 2000ADDRESS: P.O. BOX 372,
MASCOT NSW 2020ADDRESS: 80038 - POMIGLIANO D'ARCO (NA)
ITALY

OFFICE: +61-2-8273-9605

OFFICE: +61-2-8273-9600

POMIGLIANO 80038

FAX: +61-2-9252-1508

FAX: +61-2-9700-8550

OFFICE:

FAX:

ANALYST: RANDY BUTLER

1-866-581-2267 (OFFICE)

800-787-9749 (EFAX-CARDS)

EMAIL: RBUTLER@CAMPSYSTEMS.COM

316-462-2442 (FAX)

631-980-4222 (EFAX-CARDS)

WWW.CAMPSYSTEMS.COM

PROJECTED: 12 MOS. to 05-MAR-2025

AIRCRAFT	SERIAL/REGNO: 22294/VH-LCF			MODEL:	AW109SP GRAND NEW		MANUFACTURER: LEONARDO S.P.A.	
CERTIFICATION DATE: 08-APR-2013				LAST ACTUALS:			PROJECTED:	
				1446.5	A/C HRS	as of 23-JAN-2024	1806.50	
				3860	AFL	as of 23-JAN-2024	4220	
ENGINE NO. 1	SERIAL/PART: PCE-BH0658/PW207C			MODEL:	PW207C		MANUFACTURER: PRATT & WHITNEY CANADA CORP.	
INSTALLED ON: 01-NOV-2012				LAST ACTUALS:			PROJECTED:	
0	ENG. HRS	0	A/C HRS	1446.5	ENG. HRS	as of 23-JAN-2024	1806.50	
0	ENC			0	ENC	as of 18-MAY-2022	360	
				0	IMPCYC	as of 18-MAY-2022	360	
				0	CTCYC	as of 18-MAY-2022	360	
				0	PTCYC	as of 18-MAY-2022	360	
ENGINE NO. 2	SERIAL/PART: PCE-BH0663/PW207C			MODEL:	PW207C		MANUFACTURER: PRATT & WHITNEY CANADA CORP.	
INSTALLED ON: 01-NOV-2012				LAST ACTUALS:			PROJECTED:	
0	ENG. HRS	0	A/C HRS	1446.5	ENG. HRS	as of 23-JAN-2024	1806.50	
0	ENC			0	ENC	as of 18-MAY-2022	360	
				0	IMPCYC	as of 18-MAY-2022	360	
				0	CTCYC	as of 18-MAY-2022	360	
				0	PTCYC	as of 18-MAY-2022	360	



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-44-00-01-000-01		50 HOUR/60 DAY INSPECTION							Package ATA:05
	DAYS	60	23-Jan-24		23-Mar-24		19 d	23-Mar-2024(7)	41 d
	HRS	50	1446.5		1496.5		50		0
	AFL		3860						0
REF: GENERIC REFER TO APPROPRIATE MANUAL									
772110		NO. 1 ENGINE - RECORD THE ACCUMULATED CYCLES FOR EACH LOW-CYCLE FATIGUE (LCF)
COMPONENT FROM THE HELICOPTER DISPLAY SYSTEM OR DIRECTLY FROM THE DCU USING THE GROUND BASE SOFTWARE (GBS) PROGRAM. DO A CONSISTENCY CHECK							Service ATA:77
	MOS		04-Oct-23					30-Mar-2024(7)	5
	HRS	50	1422.7		(1472.7)1472.7		26.2		23.8
	ENC								
REF: MM AIRWORTHINESS									
772110		NO. 2 ENGINE - RECORD THE ACCUMULATED CYCLES FOR EACH LOW-CYCLE FATIGUE (LCF)
COMPONENT FROM THE HELICOPTER DISPLAY SYSTEM OR DIRECTLY FROM THE DCU USING THE GROUND BASE SOFTWARE (GBS) PROGRAM. DO A CONSISTENCY CHECK							Service ATA:77
	MOS		04-Oct-23					30-Mar-2024(7)	5
	HRS	50	1422.7		(1472.7)1472.7		26.2		23.8
	ENC								
REF: MM AIRWORTHINESS									
EASA 2022-0037 PARA (02)		ACCOMPLISH A QUALITATIVE AXIAL PLAY CHECK IN ACCORDANCE WITH THE INSTRUCTIONS OF PART IV OF THE ASB (GP 1 AND GP 2)							AD ATA:62
	MOS		04-Oct-23					30-Mar-2024(7)	5
	HRS	50	1422.7		1472.7		26.2		23.8
	AFL								
Disposition: MANDATORY		REF: AD							
SI62-14		ROTATING SCISSORS - EXAMINE FOR DAMAGE, CORROSION WEAR AND EXCESSIVE PLAY							Service ATA:62
	MOS	6	04-Oct-23	Adj:-1d	03-Apr-24		30 d	03-Apr-2024(2)	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
REF: AMP 0B-A-62-31-02-00A-281A-A									
SI62-15		NON-ROTATING SCISSORS - EXAMINE FOR DAMAGE, CORROSION WEAR AND EXCESSIVE PLAY							Service ATA:62
	MOS	6	04-Oct-23	Adj:-1d	03-Apr-24		30 d	03-Apr-2024(2)	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
REF: AMP 0B-A-62-31-03-00A-281A-A									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL: 3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
SR64-01 TAIL ROTOR PITCH CHANGE MECHANISM DUPLEX BEARING - GREASE									
	MOS	6	04-Oct-23	Adj:-1d	03-Apr-24		30 d	03-Apr-2024(3)	5
	HRS	100	1422.7		1522.7		76.2		23.8
	AFL		3799						61
REF: AMP 0B-B-12-20-17-00A-242A-A									
SM26-01-01 CABIN PORTABLE FIRE EXTINGUISHER - DO A CHECK OF MASS AND EXAMINE FOR CONDITION									
PN:PN-UNKNOWN	MOS	6	04-Oct-23		04-Apr-24		31 d	04-Apr-2024(2)	5
SN:UNKNOWN	HRS		1422.7						23.8
	AFL		3799						61
REF: AMP 0B-A-26-23-01-00A-281A-B									
SM26-01-01 COCKPIT PORTABLE FIRE EXTINGUISHER - DO A CHECK OF MASS AND EXAMINE FOR CONDITION									
PN:A072A02	MOS	6	04-Oct-23		04-Apr-24		31 d	04-Apr-2024(2)	5
SN:2021/03120	HRS		1422.7						23.8
	AFL		3799						61
REF: AMP 0B-A-26-23-01-00A-281A-B									
ASB 109SP-158 PART I ACCOMPLISH INSPECTION AND REPLACEMENT OF MAIN ROTOR BLADE TIP CAP, ALERT SERVICE BULLETIN PERFORM A TAPPING TEST ON MAIN ROTOR BLADE TIP CAP									
	MOS		EFF					09-Apr-2024(13)	
	HRS	T:25	EFF		1482.85 *		36.4		
	AFL								
Disposition: ALERT REF: BULLETINS									
MI62-01 NO. 1 (RED) MAIN ROTOR ELASTOMERIC BEARING - INSPECT FOR CRACKING, SEPARATION OF SHIMS, BLOWING, RUBBER POWDER AND/OR CRUMBS									
PN:109-0111-04-101	MOS		04-Oct-23					09-Apr-2024(6)	5
SN:LK3745	HRS	60	1422.7		1482.7		36.2		23.8
	AFL		3799						61
Disposition: MANDATORY REF: AMP 0B-A-62-21-00-00A-281A-A									
MI62-01 NO. 2 (YELLOW) MAIN ROTOR ELASTOMERIC BEARING - INSPECT FOR CRACKING, SEPARATION OF SHIMS, BLOWING, RUBBER POWDER AND/OR CRUMBS									
PN:109-0111-04-101	MOS		04-Oct-23					09-Apr-2024(6)	5
SN:LK3753	HRS	60	1422.7		1482.7		36.2		23.8
	AFL		3799						61
Disposition: MANDATORY REF: AMP 0B-A-62-21-00-00A-281A-A									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL: 3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
MI62-01		NO. 3 (WHITE) MAIN ROTOR ELASTOMERIC BEARING - INSPECT FOR CRACKING, SEPARATION OF SHIMS, BLOWING, RUBBER POWDER AND/OR CRUMBS							Service ATA:62
PN:109-0111-04-101	MOS		04-Oct-23					09-Apr-2024(6)	5
SN:LK3755	HRS	60	1422.7		1482.7		36.2		23.8
	AFL		3799						61
Disposition: MANDATORY REF: AMP 0B-A-62-21-00-00A-281A-A									
MI62-01		NO. 4 (BLUE) MAIN ROTOR ELASTOMERIC BEARING - INSPECT FOR CRACKING, SEPARATION OF SHIMS, BLOWING, RUBBER POWDER AND/OR CRUMBS							Service ATA:62
PN:109-0111-04-101	MOS		04-Oct-23					09-Apr-2024(6)	5
SN:LK3756	HRS	60	1422.7		1482.7		36.2		23.8
	AFL		3799						61
Disposition: MANDATORY REF: AMP 0B-A-62-21-00-00A-281A-A									
SR65-01		90-DEGREE GEARBOX - CHANGE OF OIL							Service ATA:65
	MOS	6	04-Oct-23	Adj:7d	11-Apr-24		38 d	11-Apr-2024(3)	5
	HRS	100	1422.7		1522.7		76.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-13-02-00A-292A-A									
OE21-04		ENVIRONMENTAL CONTROL SYSTEM (X64) - HEAT EXCHANGER - DO DETAILED EXAMINATION FOR CONDITION AND OBSTRUCTION							Service ATA:21
PN:PN	MOS		10-Oct-22					18-Apr-2024(4)	16.8
SN:UNKNOWN	HRS	100	1391.4		1491.4		44.9		55.1
	AFL								
REF: AMP 0B-A-21-91-02-00A-281A-A									
SR62-02		MAIN ROTOR FLOATING RING AND DROOP STOP PLATES - GREASE							Service ATA:62
	DAYS	90	23-Jan-24		22-Apr-24		49 d	22-Apr-2024(7)	41 d
	HRS	50	1446.5		1496.5		50		0
	AFL		3860						0
REF: AMP 0B-A-12-20-13-00A-242A-A									
SR62-03		SWASHPLATE (2 PLACES) - GREASE							Service ATA:62
PN:109-0134-02-105	DAYS	90	23-Jan-24		22-Apr-24		49 d	22-Apr-2024(7)	41 d
SN:V81	HRS	50	1446.5		1496.5		50		0
	AFL		3860						0
REF: AMP 0B-A-12-20-14-00A-242A-A									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
EASA 2023-0159 PARA (1)		INSPECT EACH AFFECTED PART IN ACCORDANCE WITH THE INSTRUCTIONS OF PART I OF THE ASB							AD ATA:62
	MOS		EFF					01-May-2024(13)	
	HRS	T:25	EFF		1504.53 *		58		
	AFL								
Disposition: MANDATORY			REF: AD						
05-44-00-04-000-01		800 HOUR INSPECTION							Package ATA:05
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		1505.1		58.6		741.4
	AFL		1929						1931
REF: GENERIC REFER TO APPROPRIATE MANUAL									
722101		NO. 1 ENGINE - AIR INLET SCREEN - DO A VISUAL INSPECTION OF THE SCREEN FOR BLOCKAGE AND DAMAGE. MAKE SURE THE HARDWARE THAT YOU ATTACH IS SERVICEABLE. IF THE AIR INLET SCREEN IS REMOVED DO AN INSPECTION OF THE CENTRIFUGAL IMPELLER							Service ATA:72
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
REF: MM 72-21-00									
722101		NO. 2 ENGINE - AIR INLET SCREEN - DO A VISUAL INSPECTION OF THE SCREEN FOR BLOCKAGE AND DAMAGE. MAKE SURE THE HARDWARE THAT YOU ATTACH IS SERVICEABLE. IF THE AIR INLET SCREEN IS REMOVED DO AN INSPECTION OF THE CENTRIFUGAL IMPELLER							Service ATA:72
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
REF: MM 72-21-00									
722115		NO. 1 ENGINE - COMPRESSOR INLET CASE - DO A VISUAL INSPECTION							Service ATA:72
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
REF: MM 72-21-00									
722115		NO. 2 ENGINE - COMPRESSOR INLET CASE - DO A VISUAL INSPECTION							Service ATA:72
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
REF: MM 72-21-00									
731131		NO. 1 ENGINE - REMOVE AND REPLACE ENGINE FUEL FILTER							Service ATA:73
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
REF: MM 73-21-50									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
731131			NO. 2 ENGINE - REMOVE AND REPLACE ENGINE FUEL FILTER						Service ATA:73
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: MM 73-21-50						
732131			NO. 1 ENGINE - CHECK EEC/FMM DO A MANUAL MODE RESPONSE CHECK AND DO AN OPERATIONAL CHECK OF THE ALTERNATE ENGINE SHUTDOWN SYSTEM.						Service ATA:73
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: GENERIC NO REF						
732131			NO. 2 ENGINE - CHECK EEC/FMM DO A MANUAL MODE RESPONSE CHECK AND DO AN OPERATIONAL CHECK OF THE ALTERNATE ENGINE SHUTDOWN SYSTEM.						Service ATA:73
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: GENERIC NO REF						
741101			NO. 1 ENGINE - DETAILED VISUAL INSPECTION OF ENGINE IGNITER PLUG FOR EROSION.						Service ATA:74
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: MM 74-11-00						
741101			NO. 2 ENGINE - DETAILED VISUAL INSPECTION OF ENGINE IGNITER PLUG FOR EROSION.						Service ATA:74
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: MM 74-11-00						
741103			NO. 1 ENGINE - FUNCTIONAL CHECK TO VERIFY OPERATING CAPABILITIES OF THE ENGINE IGNITER PLUG						Service ATA:74
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: MM 74-11-00						
741103			NO. 2 ENGINE - FUNCTIONAL CHECK TO VERIFY OPERATING CAPABILITIES OF THE ENGINE IGNITER PLUG						Service ATA:74
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: MM 74-11-00						



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
792101			NO. 1 ENGINE - REMOVE AND REPLACE ENGINE OIL FILTER						Service ATA:79
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: MM 79-11-00						
792101			NO. 2 ENGINE - REMOVE AND REPLACE ENGINE OIL FILTER						Service ATA:79
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		(1505.1)1505.1		58.6		741.4
	ENC								
			REF: MM 79-11-00						
CM21-03			HEATING - OC TO VERIFY THE FUNCTIONAL PATH THAT ENSURES THE SOVS ARE AUTOMATICALLY CLOSED IN THE EVENT OF OEI						Service ATA:21
	MOS		18-Jan-17					02-May-2024	85.5
	HRS	800	705.1		1505.1		58.6		741.4
	AFL		1929						1931
Disposition: CMR REF: AMP 0B-B-21-41-00-00A-320B-A									
CM23-02			COMMUNICATION - OC OF VHF2 GUARDED EMERGENCY SWITCH FUNCTION TO VERIFY THAT THERE ARE NO HIDDEN FAILURES PREVENTING THE SWITCH TO SET THE EMERGENCY VHF2 RADIO FREQUENCY						Service ATA:23
	MOS							02-May-2024	
	HRS	800	705.1		1505.1		58.6		741.4
	AFL								
Disposition: CMR REF: AMP 0B-B-23-12-00-00A-320B-A									
SI64-01			TAIL ROTOR - DO A CHECK FOR CORRECT DYNAMIC BALANCE						Service ATA:64
	MOS		04-Oct-23					20-May-2024(3)	5
	HRS	100	1422.7		1522.7		76.2		23.8
	AFL		3799						61
			REF: AMP 0B-A-18-10-02-00A-37BA-A						
05-44-00-02-000-01			200 HOUR INSPECTION						Package ATA:05
	MOS		05-Nov-20					28-May-2024(2)	40
	HRS	200	1330.6		1530.6		84.1		115.9
	AFL		3563						297
			REF: GENERIC REFER TO APPROPRIATE MANUAL						
721100			NO. 1 ENGINE - INSPECT THE P3 AIR PASSAGE OF THE SHUT-OFF VALVE FOR THE PRESENCE OF DEBRIS						Service ATA:72
	MOS		05-Nov-20					28-May-2024(2)	40
	HRS	200	1330.6		(1530.6)1530.6		84.1		115.9
	ENC								
			REF: MM 72-11-00						



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
721100			NO. 2 ENGINE - INSPECT THE P3 AIR PASSAGE OF THE SHUT-OFF VALVE FOR THE PRESENCE OF DEBRIS						Service ATA:72
	MOS		05-Nov-20					28-May-2024(2)	40
	HRS	200	1330.6		(1530.6)1530.6		84.1		115.9
	ENC								
			REF: MM 72-11-00						
732100			NO. 1 ENGINE - CHECK EEC/FUEL MANAGEMENT MODULE AUTO TO MANUAL TO AUTO MODE RESPONSE						Service ATA:73
	MOS		05-Nov-20					28-May-2024(2)	40
	HRS	200	1330.6		(1530.6)1530.6		84.1		115.9
	ENC								
			REF: MM 73-21-10						
732100			NO. 2 ENGINE - CHECK EEC/FUEL MANAGEMENT MODULE AUTO TO MANUAL TO AUTO MODE RESPONSE						Service ATA:73
	MOS		05-Nov-20					28-May-2024(2)	40
	HRS	200	1330.6		(1530.6)1530.6		84.1		115.9
	ENC								
			REF: MM 73-21-10						
732110			NO. 1 ENGINE - INSPECT THE FMM P3 NIPPLE ON THE OUTPUT SHAFT COVER FOR PRESENCE OF DEBRIS						Service ATA:73
	MOS		05-Nov-20					28-May-2024(2)	40
	HRS	200	1330.6		(1530.6)1530.6		84.1		115.9
	ENC								
			REF: MM 73-21-10						
732110			NO. 2 ENGINE - INSPECT THE FMM P3 NIPPLE ON THE OUTPUT SHAFT COVER FOR PRESENCE OF DEBRIS						Service ATA:73
	MOS		05-Nov-20					28-May-2024(2)	40
	HRS	200	1330.6		(1530.6)1530.6		84.1		115.9
	ENC								
			REF: MM 73-21-10						
SI65-03			TAIL ROTOR DRIVE SHAFT BEARINGS - EXAMINE FOR CONDITION						Service ATA:65
	MOS		16-Oct-19					11-Jun-2024	52.6
	HRS	300	1244.3		1544.3		97.8		202.2
	AFL		3346						514
			REF: GENERIC REFER TO APPROPRIATE MANUAL						
SR65-02			TAIL ROTOR DRIVE SHAFT BEARINGS (7 OFF) - GREASE						Service ATA:65
	MOS		16-Oct-19					11-Jun-2024	52.6
	HRS	300	1244.3		1544.3		97.8		202.2
	AFL		3346						514
			REF: AMP 0B-A-12-20-15-00A-242A-A						



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
720150 NO. 1 ENGINE - POWER ASSURANCE CHECK /ENGINE HEALTH TREND MONITORING									
	MOS		04-Oct-23					10-Jul-2024(2)	5
	HRS	150	1422.7		(1572.7)1572.7		126.2		23.8
	ENC								
REF: MM 71-00-00									
720150 NO. 2 ENGINE - POWER ASSURANCE CHECK /ENGINE HEALTH TREND MONITORING									
	MOS		04-Oct-23					10-Jul-2024(2)	5
	HRS	150	1422.7		(1572.7)1572.7		126.2		23.8
	ENC								
REF: MM 71-00-00									
MI53-01 FUSELAGE - INSPECT FUSELAGE FOR DELAMINATION AND DISBOND ON CRITICAL AREA									
PN:109-0300-21-101	MOS		15-Oct-18					06-Aug-2024	64.6
SN:AWPZ267	HRS	450	1149.4		1599.4		152.9		297.1
	AFL		2980						880
Disposition: MANDATORY REF: AMP 0B-B-53-10-00-00A-283A-A									
SI65-02 90-DEGREE GEARBOX - EXAMINE GEARING TEETH FOR UNUSUAL PRINTS, PITTING, SCORING, DAMAGE. EXAMINE BEARINGS FOR FREEDOM OF ROTATION AND ROUGHNESS									
	MOS		08-Apr-13					07-Aug-2024	130.9
	HRS	1600	0		1600		153.5		1446.5
	AFL		0						3860
REF: AMP 0B-A-65-21-00-00A-283B-B									
SR32-04 NOSE LANDING GEAR STRUT - FILL WITH FLUID									
	MOS		08-Apr-13					07-Aug-2024	130.9
	HRS	1600	0		1600		153.5		1446.5
	AFL		0						3860
REF: AMP 0B-A-12-20-06-00A-218A-A									
720035 NO. 1 ENGINE - OIL ANALYSIS TECHNOLOGY									
	MOS	12	04-Oct-23		04-Oct-24		214 d	30-Aug-2024	5
	HRS	200	1422.7		(1622.7)1622.7		176.2		23.8
	ENC								
REF: MM 72-00-00									
720035 NO. 2 ENGINE - OIL ANALYSIS TECHNOLOGY									
	MOS	12	04-Oct-23		04-Oct-24		214 d	30-Aug-2024	5
	HRS	200	1422.7		(1622.7)1622.7		176.2		23.8
	ENC								
REF: MM 72-00-00									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
MI64-01		NO. 1 (RED) TAIL ROTOR BLADE - INBOARD ELASTOMERIC BUSHING - INSPECT FOR CRACKING, BLOWING, RUBBER AND/OR CRUMBS							Service ATA:64
PN:709-0160V01-101	MOS		04-Oct-23					30-Aug-2024	5
SN:7541	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
Disposition: MANDATORY		REF: AMP 0B-A-64-11-01-00A-281A-B							
MI64-01		NO. 1 (RED) TAIL ROTOR BLADE - OUTBOARD ELASTOMERIC BUSHING - INSPECT FOR CRACKING, BLOWING, RUBBER AND/OR CRUMBS							Service ATA:64
PN:709-0160V01-101	MOS		04-Oct-23					30-Aug-2024	5
SN:7409	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
Disposition: MANDATORY		REF: AMP 0B-A-64-11-01-00A-281A-B							
MI64-01		NO. 2 (WHITE) TAIL ROTOR BLADE - INBOARD ELASTOMERIC BUSHING - INSPECT FOR CRACKING, BLOWING, RUBBER AND/OR CRUMBS							Service ATA:64
PN:709-0160V01-101	MOS		04-Oct-23					30-Aug-2024	5
SN:7476	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
Disposition: MANDATORY		REF: AMP 0B-A-64-11-01-00A-281A-B							
MI64-01		NO. 2 (WHITE) TAIL ROTOR BLADE - OUTBOARD ELASTOMERIC BUSHING - INSPECT FOR CRACKING, BLOWING, RUBBER AND/OR CRUMBS							Service ATA:64
PN:709-0160V01-101	MOS		04-Oct-23					30-Aug-2024	5
SN:7683	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
Disposition: MANDATORY		REF: AMP 0B-A-64-11-01-00A-281A-B							
SI53-09		TAIL ROTOR DRIVE SHAFT SUPPORTS AND ADJACENT FUSELAGE / TAIL AREA - EXAMINE FOR CORROSION AND FUELAGES/TAIL AREA FOR CRACKS							Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	30-Aug-2024	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
		REF: GENERIC REFER TO APPROPRIATE MANUAL							
SI53-13		FORWARD AND AFT MAIN GEARBOX FITTINGS, LEFT/RIGHT - DO A VISUAL INSPECTION FOR CORROSION, CRACKS AND PROPER CONDITION OF JOINTS.							Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	30-Aug-2024	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
		REF: AMP 0B-A-53-10-00-00A-281D-A							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
SI63-01 MAIN TRANSMISSION CHIP DETECTORS - DO OPERATIONAL TEST									
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	30-Aug-2024	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
REF: AMP 0B-A-63-41-00-00A-320A-A									
SI65-01 90-DEGREE GEARBOX CHIP DETECTOR - DO OPERATIONAL TEST									
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	30-Aug-2024	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
REF: AMP 0B-A-65-41-01-00A-320A-A									
SR29-02 FLIGHT CONTROL HYDRAULIC SYSTEM ACCUMULATORS (2 OFF) - FILL WITH NITROGEN									
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	30-Aug-2024	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-20-01-00A-214A-A, AMP 0B-A-12-20-02-00A-214A-A									
SR67-01 MAIN ROTOR SERVO ACTUATORS (3 OFF) - GREASE									
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	30-Aug-2024	5
	HRS	200	1422.7		1622.7		176.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-20-16-00A-242A-A									
SB 109SP-159 PART IV ACCOMPLISH AMPI UPDATED, SERVICE BULLETIN IN ACCORDANCE WITH AMPI DM 0B-B-05-45-00-00A-028A-D, APPLY THE MAINTENANCE TASK 53-14 "PERFORM A DETAIL INSPECTION OF THE UPPER DECK AREA AND PANELS FOR CRACKS, CORROSION, DEBONDING AND DAMAGE";.									
	MOS	T:12	EFF		10-Oct-24 *		220 d	05-Sep-2024	
	HRS	T:200	EFF		1628.83 *		182.3		
	AFL								
Disposition: RECOMMENDED REF: BULLETINS									
SI53-14 UPPER DECK - PERFORM A DETAIL INSPECTION OF THE UPPER DECK AREA AND PANELS FOR CRACKS, CORROSION, DEBONDING AND DAMAGE									
	MOS	T:12	EFF		10-Oct-24 *		220 d	05-Sep-2024	130.9
	HRS	T:200	EFF		1628.83 *		182.3		1446.5
	AFL								3860
REF: GENERIC NO REFERENCE									
SI53-15 UPPER HORIZONTAL BEAM STA 1815 - PERFORMA DETAIL INSPECTION FOR CRACKS TO THE UPPERHORIZONTAL BEAM									
	MOS	T:12	EFF		10-Oct-24 *		220 d	05-Sep-2024	130.9
	HRS	T:200	EFF		1628.83 *		182.3		1446.5
	AFL								3860
REF: GENERIC NO REFERENCE									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-44-00-06-000-01		12 MONTH INSPECTION							Package ATA:05
	MOS	12	04-Oct-23	Adj:-11d	23-Sep-24		203 d	23-Sep-2024	5
	HRS		1422.7						23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
34-11-00-00-364-01		PITOT-STATIC SYSTEM – LEAK CHECK							Service ATA:34
	MOS	24	23-Sep-22		23-Sep-24		203 d	23-Sep-2024	17.4
	HRS		1391.4						55.1
	AFL								
REF: AMP 0B-B-34-11-00-00A-364A-A									
34-13-00-00-340-01		TEST NO. 1 AIR DATA COMPUTER							Service ATA:34
PN:PN	MOS	24	23-Sep-22		23-Sep-24		203 d	23-Sep-2024	17.4
SN:UNKNOWN	HRS		1391.4						55.1
	AFL								
REF: AMP 0B-B-34-13-00-00A-340A-A									
34-14-00-00-340-01		TEST NO. 2 AIR DATA COMPUTER							Service ATA:34
PN:PN	MOS	24	23-Sep-22		23-Sep-24		203 d	23-Sep-2024	17.4
SN:UNKNOWN	HRS		1391.4						55.1
	AFL								
REF: AMP 0B-B-34-14-00-00A-340A-A									
34-31-00-00-300-01		TEST RADAR ALTIMETER							Service ATA:34
PN:PN	MOS	24	23-Sep-22		23-Sep-24		203 d	23-Sep-2024	17.4
SN:UNKNOWN	HRS		1391.4						55.1
	AFL								
REF: AMP 0B-B-34-31-00-00A-320A-A, AMP 0B-B-34-31-00-00A-340A-A									
34-52-00-00-340-01		AIR TRAFFIC CONTROL (ATC) TRANSPONDER - TEST/INSPECT							Service ATA:34
PN:622-9352-409	MOS	24	23-Sep-22		23-Sep-24		203 d	23-Sep-2024	17.4
SN:4BVWW	HRS		1391.4						55.1
	AFL								
REF: AMP 0B-D-34-52-00-00A-340A-A, AMP 0B-D-34-52-00-00A-340C-A									
CM21-01		HEATING - DVI HOT AIR DELIVERY TUBES							Service ATA:21
PN:PN	MOS	24	23-Sep-22		23-Sep-24		203 d	23-Sep-2024	17.4
SN:UNKNOWN	HRS		1391.4						55.1
	AFL								
Disposition: CMR REF: AMP 0B-B-21-41-16-00A-281B-A									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
OE25-01 EMERGENCY LOCATOR TRANSMITTER SYSTEM - ELT CASE AND ANTENNA - EXAMINE FOR CORRECT INSTALLATION									
	MOS	12	04-Oct-23	Adj:-11d	23-Sep-24		203 d	23-Sep-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI24-01 BATTERY (REMOVAL NECESSARY) - DO RECONDITIONING SERVICE									
PN:33181-001	MOS	12	04-Oct-23	Adj:-11d	23-Sep-24		203 d	23-Sep-2024	5
SN:11202608	HRS	900	1422.7		2322.7		876.2		23.8
	AFL		3799						61
REF: AMP 0B-B-24-32-01-00A-200A-A									
SI52-01 COCKPIT DOOR EMERGENCY RELEASE MECHANISMS - EXAMINE FOR CORRECT OPERATION									
	MOS	12	04-Oct-23	Adj:-11d	23-Sep-24		203 d	23-Sep-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-B-52-13-00-00A-320A-A									
SI53-02 TAIL BOOM INTERNAL AREA AND RELATED FUSELAGE BRACKETS - EXAMINE FOR CRACKS, CORROSION AND DISTORTION									
	MOS	12	04-Oct-23	Adj:-11d	23-Sep-24		203 d	23-Sep-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-53-40-00-00A-281A-A									
SI53-04 INTERNAL SURFACE OF STRUCTURE BELOW ENGINE MOUNT FITTINGS (LEFT SIDE OF NUMBER 1 ENGINE AND RIGHT SIDE OF NUMBER 2 ENGINE) - EXAMINE FOR CRACKS									
	MOS	12	04-Oct-23	Adj:-11d	23-Sep-24		203 d	23-Sep-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-53-10-00-00A-281A-A									
DT24-01 NO. 1 STARTER/GENERATOR - STARTER GENERATOR BRUSH - DISCARD									
PN:200SGL147Q-3-1	MOS		15-Oct-18					26-Sep-2024	64.6
SN:500147XL2	HRS	500	1149.4		1649.4		202.9		297.1
	AFL		2980						880
Disposition: DISCARD REF:									
DT24-01 NO. 2 STARTER/GENERATOR - STARTER GENERATOR BRUSH - DISCARD									
PN:200SGL147Q-3-1	MOS		15-Oct-18					26-Sep-2024	64.6
SN:S00146XL2	HRS	500	1149.4		1649.4		202.9		297.1
	AFL		2980						880
Disposition: DISCARD REF:									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
DT26-02 (EIS)		NO. 1 FIRE EXTINGUISHER, LOWER CARTRIDGE - DISCARD (TIME IN SERVICE)							Service ATA:26
PN:30600-22	MOS	144	01-Oct-12		01-Oct-24		211 d	01-Oct-2024	137.1
SN:NSN	HRS								
	AFL								
Disposition: DISCARD		REF: AMP 0B-A-26-21-01-01A-921A-A							
DT26-02 (EIS)		NO. 1 FIRE EXTINGUISHER, UPPER CARTRIDGE - DISCARD (TIME IN SERVICE)							Service ATA:26
PN:30600-22	MOS	144	01-Oct-12		01-Oct-24		211 d	01-Oct-2024	137.1
SN:NSN	HRS								
	AFL								
Disposition: DISCARD		REF: AMP 0B-A-26-21-01-01A-921A-A							
DT26-02 (EIS)		NO. 2 FIRE EXTINGUISHER, LOWER CARTRIDGE - DISCARD (TIME IN SERVICE)							Service ATA:26
PN:30600-22	MOS	144	01-Oct-12		01-Oct-24		211 d	01-Oct-2024	137.1
SN:NSN	HRS								
	AFL								
Disposition: DISCARD		REF: AMP 0B-A-26-22-01-01A-921A-A							
DT26-02 (EIS)		NO. 2 FIRE EXTINGUISHER, UPPER CARTRIDGE - DISCARD (TIME IN SERVICE)							Service ATA:26
PN:30600-22	MOS	144	01-Oct-12		01-Oct-24		211 d	01-Oct-2024	137.1
SN:NSN	HRS								
	AFL								
Disposition: DISCARD		REF: AMP 0B-A-26-22-01-01A-921A-A							
250001 ^U		REPLACE BATTERY IN PASSENGER HEADSET							Service ATA:25
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	AFL		3799						61
		REF:							
714001		NO. 1 ENGINE - GENERAL VISUAL CHECK OF ENGINE FUEL/OIL TUBES FOR SECURITY, FUEL AND/OR OIL LEAKS.							Service ATA:71
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
		REF: GENERIC NO REF							
714001		NO. 2 ENGINE - GENERAL VISUAL CHECK OF ENGINE FUEL/OIL TUBES FOR SECURITY, FUEL AND/OR OIL LEAKS.							Service ATA:71
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
		REF: GENERIC NO REF							



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
742001			NO. 1 ENGINE - GENERAL VISUAL CHECK OF IGNITION CABLE WIRES FOR EVIDENCE OF CHAFING,CRACKS,CORROSION AND WEAR.						Service ATA:74
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: GENERIC NO REF									
742001			NO. 2 ENGINE - GENERAL VISUAL CHECK OF IGNITION CABLE WIRES FOR EVIDENCE OF CHAFING,CRACKS,CORROSION AND WEAR.						Service ATA:74
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: GENERIC NO REF									
742141			NO. 1 ENGINE - CHECK CONNECTOR SECURITY AND APPLY ELECTRICAL CONTACT ENHANCER TO THE CONNECTORS OF THE ELECTRICAL WIRING HARNESS						Service ATA:74
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: GENERIC NO REF									
742141			NO. 2 ENGINE - CHECK CONNECTOR SECURITY AND APPLY ELECTRICAL CONTACT ENHANCER TO THE CONNECTORS OF THE ELECTRICAL WIRING HARNESS						Service ATA:74
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: GENERIC NO REF									
772101			NO. 1 ENGINE - GENERAL VISUAL CHECK OF ENGINE T6/T1 WIRING HARNESSES FOR EVIDENCE OF CHAFING, CRACKS, CORROSION AND WEAR. VERIFY TERMINAL JUNCTION NUTS ARE SECURED. DO A HEAT RESPONSE CHECK.						Service ATA:77
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: MM 77-21-00									
772101			NO. 2 ENGINE - GENERAL VISUAL CHECK OF ENGINE T6/T1 WIRING HARNESSES FOR EVIDENCE OF CHAFING, CRACKS, CORROSION AND WEAR. VERIFY TERMINAL JUNCTION NUTS ARE SECURED. DO A HEAT RESPONSE CHECK.						Service ATA:77
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: MM 77-21-00									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
772111 NO. 1 ENGINE - VISUAL CHECK ON WIRES FOR EVIDENCE OF CHAFING, CRACKS, CORROSION AND WEAR.									
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: GENERIC NO REF									
772111 NO. 2 ENGINE - VISUAL CHECK ON WIRES FOR EVIDENCE OF CHAFING, CRACKS, CORROSION AND WEAR.									
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: GENERIC NO REF									
793101 NO. 1 ENGINE - OPERATIONAL CHECK OF ENGINE CHIP DETECTOR									
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: MM 79-31-00									
793101 NO. 2 ENGINE - OPERATIONAL CHECK OF ENGINE CHIP DETECTOR									
	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
	HRS		1422.7						23.8
	ENC								
REF: MM 79-31-00									
DT25-02 FIRST AID KIT - DISCARD									
PN:PN	MOS	DUE	10-Oct-22		04-Oct-24 (M)		214 d	04-Oct-2024	16.8
SN:UNKNOWN	HRS		1391.4						55.1
	AFL								
Disposition: DISCARD REF: GENERIC REFER TO APPROPRIATE MANUAL									
DT28-01 NO. 1 FUEL FILTER ELEMENT - DISCARD									
PN:KD651510	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
SN:UNKNOWN	HRS	400	1422.7		1822.7		376.2		23.8
	AFL								
Disposition: DISCARD REF:									
DT28-01 NO. 2 FUEL FILTER ELEMENT - DISCARD									
PN:KD651510	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
SN:UNKNOWN	HRS	400	1422.7		1822.7		376.2		23.8
	AFL								
Disposition: DISCARD REF:									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
OE21-01		ENVIRONMENTAL CONTROL SYSTEM (X64) - BLEED AIR LINES, PIPES, JOINTS AND FITTINGS - EXAMINE FOR CONDITION AND SECURITY							Service ATA:21
PN:PN	MOS	12	04-Oct-23		04-Oct-24		214 d	04-Oct-2024	5
SN:UNKNOWN	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
DT63-01 (DOI)		NO. 1 TOOTHED BELT - DISCARD (DATE OF INSTALLATION)							Service ATA:63
PN:109-0455-09-103	MOS	24	10-Oct-22		10-Oct-24		220 d	10-Oct-2024	16.8
SN:74410	HRS	800	1391.4		2191.4		744.9		55.1
	AFL								
Disposition: DISCARD		REF: AMP 0B-A-63-23-01-00A-520A-A, AMP 0B-A-63-23-01-00A-720A-A							
DT63-01 (DOI)		NO. 2 TOOTHED BELT - DISCARD (DATE OF INSTALLATION)							Service ATA:63
PN:109-0455-09-103	MOS	24	10-Oct-22		10-Oct-24		220 d	10-Oct-2024	16.8
SN:74406	HRS	800	1391.4		2191.4		744.9		55.1
	AFL								
Disposition: DISCARD		REF: AMP 0B-A-63-23-02-00A-520A-A, AMP 0B-A-63-23-02-00A-720A-A							
SB 109SP-159 PART III		ACCOMPLISH AMPI UPDATED, SERVICE BULLETIN IN ACCORDANCE WITH AMPI DM 0B-B-05-45-00-00A-028A-D, APPLY THE MAINTENANCE TASK 53-09 "EXAMINE ALL TAIL ROTOR DRIVE SHAFT SUPPORTS FOR CONDITION AND CORROSION INCLUDING ADJACENT FUSELAGE/TAIL AREA FOR CRACKS"							Bulletin ATA:05
	MOS	T:12	EFF		10-Oct-24 * (M)		220 d	10-Oct-2024	
	HRS	T:400	EFF		1822.7 * (M)		376.2		
	AFL								
Disposition: RECOMMENDED		REF: BULLETINS							
SI32-03		MAIN LANDING GEAR COMPARTMENTS AND EXTENSION ACTUATORS (ACTUATORS REMOVAL NECESSARY) - DO A CHECK FOR CONDITION, SECURITY, LEAKS, CLEANLINESS AND CORROSION.							Service ATA:32
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI32-04		MAIN LANDING GEAR (HELICOPTER ON JACKS) - EXAMINE FOR UNUSUAL PLAY, CONDITION, CRACKS, DISTORTION, CORROSION AND SECURITY.							Service ATA:32
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-32-11-00-00A-281A-A									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
SI32-05		MAIN LANDING GEAR SHOCK ABSORBER - DO A DIMENSIONAL CHECK OF SHOCK ABSORBER HEIGHT							Service ATA:32
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-32-10-00-00A-361A-A									
SI52-02		MAINTENANCE STEPS AND RESTRAINT CABLES - EXAMINE FOR CONDITION, SECURITY AND INTEGRITY							Service ATA:52
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI53-03		TAIL BOOM INTERNAL AREA, STABILIZER ATTACHMENT AREA AND RELATED LOCKING SYSTEM - EXAMINE FOR SECURITY AND CRACKS. EXAMINE ADJACENT AREAS FOR DISTORTION, CRACKS AND DEFECTIVE AND/OR MISSING RIVETS.							Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI53-05		FUSELAGE INTERNAL SURFACES - EXAMINE FOR CONDITION, CRACKS, CORROSION AND DISTORTION. THIS IS VERY IMPORTANT IN AREAS ADJACENT TO BATTERY AND TO ATTACHMENT POINTS OF TAIL BOOM							Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI53-06		FUSELAGE EXTERNAL SURFACES - EXAMINE FOR CONDITION, CRACKS CORROSION, DISTORTION AND DEFECTIVE AND/OR MISSING RIVETS. INSPECTION INCLUDES VISIBLE PARTS OF ALL ANTENNAS INSTALLATIONS AND THEIR SUPPORTS, GASKETS AND BONDING DEVICES FOR CORROSION, GOOD CONDITION AND PROPER ADHESION TO THE FUSELAGE.							Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI53-07		TAIL BOOM EXTERNAL SURFACES - EXAMINE FOR CONDITION, CRACKS CORROSION, DISTORTION AND DEFECTIVE AND/OR MISSING RIVETS ON UPPER FIN. INSPECTION INCLUDES VISIBLE PARTS OF ALL ANTENNAS INSTALLATIONS AND THEIR SUPPORTS, GASKETS AND BONDING DEVICES FOR CORROSION, GOOD CONDITION AND PROPER ADHESION TO THE TAIL.							Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
SI53-08	STABILIZERS - EXAMINE FOR CONDITION, DENTS, CORROSION, DEFECTIVE AND/OR MISSING RIVETS								Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI53-10	FUSELAGE STRUCTURE AT STA 4460 (109-0344-23-101/102 AND 109-0332-34-101/102) - EXAMINE FOR CRACKS, DENTS AND MISSING OR LOOSE RIVETS AND SCREWS								Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-B-53-10-00-00A-281C-A									
SI53-11	FUSELAGE STRUCTURE AT STA 4327 (109-0332-07-101/102) - EXAMINE FOR CRACKS, DENTS AND MISSING OR LOOSE RIVETS AND SCREWS								Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-B-53-10-00-00A-281C-A									
SI53-12	FUSELAGE STRUCTURE AT STA 2164.8 (109-0332-29-103/104) - EXAMINE FOR CRACKS, DENTS AND MISSING OR LOOSE RIVETS AND SCREWS.								Service ATA:53
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-B-53-10-00-00A-281C-A									
SI63-03	FAN DRIVE BELTS - DO A CHECK OF BELT TENSION								Service ATA:63
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-63-23-00-00A-369A-A									
SI63-04	OIL COOLER FAN ATTACHMENT FLANGES (DISASSEMBLY NOT NECESSARY) - EXAMINE FOR CONDITION								Service ATA:63
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SI71-01	FUEL AND OIL HOSES - EXAMINE FOR CONDITION AND CHAFING								Service ATA:71
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
SI71-02	TUBES AND ELECTRICAL WIRING - EXAMINE FOR CONDITION, CHAFING, LEAKS AND SECURITY OF CONNECTIONS								Service ATA:71
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: GENERIC REFER TO APPROPRIATE MANUAL									
SR29-01	UTILITY HYDRAULIC SYSTEM ACCUMULATORS (2 OFF) - FILL WITH NITROGEN								Service ATA:29
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-20-03-00A-214A-A, AMP 0B-A-12-20-04-00A-214A-A, AMP 0B-A-12-20-21-00A-214A-A									
SR32-01	MAIN LANDING GEAR STRUT TORQUE LINKS - GREASE								Service ATA:32
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-20-05-00A-242A-A									
SR32-03	MAIN LANDING GEAR STRUTS (2 OFF) - FILL WITH NITROGEN								Service ATA:32
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-20-05-00A-218A-A, AMP 0B-A-12-20-05-00A-214A-A									
SR63-01	MAIN TRANSMISSION - CHANGE OF OIL								Service ATA:63
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-13-01-00A-292A-A									
SR67-02	MAIN ROTOR SERVO ACTUATOR LEVERS (3 OFF) - APPLY SURFACE PROTECTION								Service ATA:67
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-20-18-00A-259A-A									
SR67-03	TAIL ROTOR SERVO ACTUATOR LEVER - APPLY SURFACE PROTECTION								Service ATA:67
	MOS	12	04-Oct-23	Adj:6d	10-Oct-24		220 d	10-Oct-2024	5
	HRS	400	1422.7		1822.7		376.2		23.8
	AFL		3799						61
REF: AMP 0B-A-12-20-19-00A-259A-A									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
OE26-02 NO. 1 ENGINE COMPARTMENT FIRE EXTINGUISHING SYSTEM - BOTTLE CARTRIDGES - DO BRIDGE WIRE RESISTANCE TEST Service ATA:26									
	MOS	36	11-Oct-21		11-Oct-24		221 d	11-Oct-2024	28.8
	HRS		1363.7						82.8
	AFL		3633						227
REF: AMP 0B-A-26-21-01-01A-366A-B									
OE26-02 NO. 2 ENGINE COMPARTMENT FIRE EXTINGUISHING SYSTEM - BOTTLE CARTRIDGES - DO BRIDGE WIRE RESISTANCE TEST Service ATA:26									
	MOS	36	11-Oct-21		11-Oct-24		221 d	11-Oct-2024	28.8
	HRS		1363.7						82.8
	AFL		3633						227
REF: AMP 0B-A-26-22-01-01A-366A-B									
SI32-01 LANDING GEAR ACTUATORS (HELICOPTERS WHICH OPERATE OVER SEA AND/OR IN HIGH HUMIDITY) - EXAMINE FOR CORROSION AND DAMAGE. Service ATA:32									
	MOS	36	11-Oct-21	Adj:4d	15-Oct-24		225 d	15-Oct-2024	28.8
	HRS	1200	1363.7		2563.7		1117.2		82.8
	AFL		3633						227
REF: AMP 0B-A-32-00-00-00A-283A-A									
SR32-03 MAIN LANDING GEAR STRUTS (2 OFF) - FILL WITH FLUID Service ATA:32									
	MOS	36	11-Oct-21	Adj:4d	15-Oct-24		225 d	15-Oct-2024	28.8
	HRS	1600	1363.7		2963.7		1517.2		82.8
	AFL		3633						227
REF: AMP 0B-A-12-20-05-00A-218A-A									
DT63-01 (DOE) NO. 1 TOOTHED BELT - DISCARD (DATE OF EXPIRATION) Service ATA:63									
PN:109-0455-09-103	MOS	DUE	23-Sep-22		30-Nov-24 (M)		271 d	30-Nov-2024	17.4
SN:74410	HRS		1391.4						55.1
	AFL								
Disposition: DISCARD REF: AMP 0B-A-63-23-01-00A-520A-A, AMP 0B-A-63-23-01-00A-720A-A									
DT63-01 (DOE) NO. 2 TOOTHED BELT - DISCARD (DATE OF EXPIRATION) Service ATA:63									
PN:109-0455-09-103	MOS	DUE	23-Sep-22		30-Nov-24 (M)		271 d	30-Nov-2024	17.4
SN:74406	HRS		1391.4						55.1
	AFL								
Disposition: DISCARD REF: AMP 0B-A-63-23-02-00A-520A-A, AMP 0B-A-63-23-02-00A-720A-A									
05-44-00-03-000-01 400 HOUR INSPECTION Package ATA:05									
	MOS		05-Nov-20					17-Dec-2024	40
	HRS	400	1330.6		1730.6		284.1		115.9
	AFL		3563						297
REF: GENERIC REFER TO APPROPRIATE MANUAL									



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
SB PW200-77-28373		NO. 1 ENGINE - INSPECTION/REPLACEMENT OF T1 SENSOR WIRING HARNESS, SERVICE BULLETIN							Bulletin ATA:77
	MOS	T:12	EFF		21-Dec-24 *		292 d	21-Dec-2024	
	HRS								
	ENC								
Disposition: CATEGORY 3		REF: BULLETINS							
SB PW200-77-28373		NO. 2 ENGINE - INSPECTION/REPLACEMENT OF T1 SENSOR WIRING HARNESS, SERVICE BULLETIN							Bulletin ATA:77
	MOS	T:12	EFF		21-Dec-24 *		292 d	21-Dec-2024	
	HRS								
	ENC								
Disposition: CATEGORY 3		REF: BULLETINS							
731001		NO. 1 ENGINE - CLEAN/FUNCTIONAL CHECK ENGINE FUEL NOZZLES							Service ATA:73
	MOS		18-Jul-17					08-Jan-2025	79.5
	HRS	900	852		(1752)1752		305.5		594.5
	ENC								
		REF: GENERIC NO REF							
731001		NO. 2 ENGINE - CLEAN/FUNCTIONAL CHECK ENGINE FUEL NOZZLES							Service ATA:73
	MOS		18-Jul-17					08-Jan-2025	79.5
	HRS	900	852		(1752)1752		305.5		594.5
	ENC								
		REF: GENERIC NO REF							
731003		NO. 1 ENGINE - INSPECT FUEL NOZZLE INLET SCREENS FOR PRESENCE OF DEBRIS							Service ATA:73
	MOS		18-Jul-17					08-Jan-2025	79.5
	HRS	900	852		(1752)1752		305.5		594.5
	ENC								
		REF: GENERIC NO REF							
731003		NO. 2 ENGINE - INSPECT FUEL NOZZLE INLET SCREENS FOR PRESENCE OF DEBRIS							Service ATA:73
	MOS		18-Jul-17					08-Jan-2025	79.5
	HRS	900	852		(1752)1752		305.5		594.5
	ENC								
		REF: GENERIC NO REF							
ASB 109SP-158 PART II		ACCOMPLISH INSPECTION AND REPLACEMENT OF MAIN ROTOR BLADE TIP CAP, ALERT SERVICE BULLETIN REMOVE FROM THE HELICOPTER THE AFFECTED MAIN ROTOR BLADE AND SEND IT TO AN AUTHORIZED BLADE REPAIR CENTER FOR APPLICATION OF PART III OF THIS SB							Bulletin ATA:62
	MOS		EFF					14-Jan-2025	
	HRS	T:300	EFF		1757.85 *		311.4		
	AFL								
Disposition: ALERT		REF: BULLETINS							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: AW109SP GRAND NEW Serial: 22294 RegNo: VH-LCF HRS: 1446.5 AFL:
3860 As Of: 23-Jan-2024 Operator: WALKER AIR SERVICES PTY LIMITED

Report Date: 05-Mar-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
EASA 2023-0159 PARA (3)		REPLACE EACH AFFECTED PART WITH A SERVICEABLE PART IN ACCORDANCE WITH THE INSTRUCTIONS OF PART II OF THE ASB							AD ATA:62
	MOS		EFF					05-Feb-2025	
	HRS	T:300	EFF		1779.53 *		333		
	AFL								
Disposition: MANDATORY		REF: AD							
CO67-01		RED MAIN ROTOR SERVO ACTUATOR - OVERHAUL							Service ATA:67
PN:109-0110-42-134	MOS		08-Apr-13					26-Feb-2025	130.9
SN:4426	HRS	1800	0		1800		353.5		1446.5
	AFL		0						3860
Disposition: OVERHAUL		REF:							
CO67-02		YELLOW MAIN ROTOR SERVO ACTUATOR - OVERHAUL							Service ATA:67
PN:109-0110-42-135	MOS		08-Apr-13					26-Feb-2025	130.9
SN:6429	HRS	1800	0		1800		353.5		1446.5
	AFL		0						3860
Disposition: OVERHAUL		REF:							
CO67-03		BLUE MAIN ROTOR SERVO ACTUATOR - OVERHAUL							Service ATA:67
PN:109-0110-42-136	MOS		08-Apr-13					26-Feb-2025	130.9
SN:8426	HRS	1800	0		1800		353.5		1446.5
	AFL		0						3860
Disposition: OVERHAUL		REF:							
CO67-04		TAIL ROTOR SERVO ACTUATOR - OVERHAUL							Service ATA:67
PN:109-0040-51-103	MOS		08-Apr-13					26-Feb-2025	130.9
SN:1998	HRS	1800	0		1800		353.5		1446.5
	AFL		0						3860
Disposition: OVERHAUL		REF:							