



DueList Report

CL-604

S/N 5592 VH-L2B

OWNER: BELUGA CAPITAL MANAGEMENT PTY LTD	OPERATOR: EXECUJET AUSTRALIA PTY LTD	OPERATOR: EXECUJET MRO SERVICES AUSTRALIA PTY LTD	CAMO: JET DILIGENCE PTY LTD
ADDRESS: LEVEL 1, 15 BLUE STREET NORTH SYDNEY NSW 2060	ADDRESS: HANGAR 394 MASCOT NSW 2020	ADDRESS: HANGAR 394, ROSS SMITH AVENUE SYDNEY NSW 2020	ADDRESS: 21 NEVILLE STREET MARRICKVILLE NSW 2204
OFFICE: +61497700135	OFFICE: 011-61-2-9693-0800	OFFICE: +61 2 9693 0800	OFFICE: +61 497 700 135
FAX:	FAX: 011-61-2-9693-0889	FAX:	FAX:
ANALYST: KOSTA KANELLAKOS	+1-514-636-2160 (DIRECT)	800-787-9749 (EFAX-CARDS)	
EMAIL: KKANELLAKOS@CAMPSYSTEMS.COM	+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)	
	WWW.CAMPSYSTEMS.COM		
PROJECTED: 25 MOS. to 08/01/2028			

AIRCRAFT	SERIAL / REGNO: 5592/VH-L2B	MODEL: CL-604	MANUFACTURER: BOMBARDIER AVIATION
	CERTIFICATION DATE: 20-SEP-2004	LAST ACTUALS:	PROJECTED:
		7603:15 A/C HRS as of 30-JUN-2026	8103:38
		5408 AFL as of 30-JUN-2026	5658
		6303 APH as of 30-JUN-2026	6803:23
		6235 APS as of 30-JUN-2026	7235
APU	SERIAL / PART: P-799C/3800804-1	MODEL: GTCP 36-150 (CL)	MANUFACTURER: HONEYWELL
	INSTALLED ON: 09-OCT-2006	LAST ACTUALS:	PROJECTED:
	960 APU HRS 1088:18 A/C HRS	6303 APU HRS as of 30-JUN-2026	6803:23
	0 APUS	6235 APUS as of 30-JUN-2026	7235
ENGINE NO. 1	SERIAL / PART: 950199/6089T11G01	MODEL: CF-34-3B (CIMMS)	MANUFACTURER: GENERAL ELECTRIC
	INSTALLED ON: 20-SEP-2004	LAST ACTUALS:	PROJECTED:
	0 ENG. HRS 0 A/C HRS	7603:15 ENG. HRS as of 30-JUN-2026	8103:38
	0 ENC	5415 ENC as of 30-JUN-2026	5665
ENGINE NO. 2	SERIAL / PART: 950200/6089T11G01	MODEL: CF-34-3B (CIMMS)	MANUFACTURER: GENERAL ELECTRIC
	INSTALLED ON: 20-SEP-2004	LAST ACTUALS:	PROJECTED:
	0 ENG. HRS 0 A/C HRS	7603:15 ENG. HRS as of 30-JUN-2026	8103:38
	0 ENC	5414 ENC as of 30-JUN-2026	5664



New Requirement/Flagged Items

Operator Review and Action Required

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD
These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

Report Date: 02-Jul-2026

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition	
				Current	Change To			
TCCA CF-2026-21 PART I		SPECIAL DETAILED INSPECTION OF THE STRUCTURE AROUND THE PASSENGER DOOR					AD	ATA:53
		MOS					MANDATORY	
		HRS						
		AFL	T:7800			7800		
NEW REQUIREMENT ADDED ON 22-MAY-26. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: AD			
FAA 2026-13-02 PARA (H)		AIRPLANE FLIGHT MANUAL (AFM) REVISION					AD	ATA:31
	01-Jul-26	MOS	T:BF/F	01-Jul-26			MANDATORY	
		HRS						
		AFL						
NEW REQUIREMENT ADDED ON 30-JUN-26. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: AD			

Name: _____ Signature: _____ Cert.# _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
45-45-CUS-9001 ^U DOWNLOAD MDC FAULT HISTORY AND SERVICE MESSAGES HISTORY AND ERASE									
	MOS	2 (+30d/-30d)	09-Apr-26		09-Jun-26	09-Jul-26	TOL (+8 d)	01-Jul-2026(13)	Service ATA:45 2.7
	HRS		7581:06						22:09
	AFL		5384						24
Disposition: CUSTOMER CODE			REF:						WO#: 5592-26-14
25-00-MID-9658 ^U INSPECT -(PBE)- THE CASE FOR CRACKS,DENTS, AND DISTORSION. INSPECT ALSO SEALED BAG TO ENSURE THAT A VACUUM LOSS HAS NOT OCCURED, THE HUMIDITY INDICATOR IS BLUE, AND THE RECOMMENDED SERVICE LIFE HAS NOT EXPIRED.									
	MOS	3	09-Apr-26		09-Jul-26		8 d	09-Jul-2026(9)	Service ATA:25 2.7
	HRS		7581:06						22:09
	AFL		5384						24
			REF:						WO#: 5592-26-14
28-CUS-002 ^U PERFORM FUELSTAT RESINAE FUEL TEST (PN HR-2-011)									
	MOS	3 (+30d/-30d)	09-Apr-26		09-Jul-26	08-Aug-26	8 d (+30)	09-Jul-2026(9)	Service ATA:28 2.7
	HRS		7581:06						22:09
	AFL		5384						24
			REF:						WO#: 5592-26-14
34-00-CUS-9001 ^U CHECK EGPWS TERRAIN DATABASE REVISION STATUS									
	MOS	3 (+30d/-30d)	09-Apr-26		09-Jul-26	08-Aug-26	8 d (+30)	09-Jul-2026(9)	Service ATA:34 2.7
	HRS		7581:06						22:09
	AFL		5384						24
Disposition: CUSTOMER CODE			REF:						WO#: 5592-26-14
38-00-MID-9064 ^U REPLACE WATER FILTER									
	MOS	3	09-Apr-26		09-Jul-26		8 d	09-Jul-2026(9)	Service ATA:38 2.7
	HRS		7581:06						22:09
	AFL		5384						24
Disposition: CUSTOMER CODE			REF:						WO#: 5592-26-14
05-CUS-9002 ^U REVIEW THE APPROVED SYSTEM OF MAINTENANCE (SOM)									
	MOS	12			11-Jul-26 (M)		10 d	11-Jul-2026	Service ATA:05
	HRS								
	AFL								
			REF:						
050040 6 MONTH CHECK									
	MOS	6 (+10%/-10%)	16-Jan-26		16-Jul-26	03-Aug-26	15 d (+18)	16-Jul-2026(5)	Package ATA:05 5.5
	HRS		7521:14						82:01
	AFL		5324						84
			REF: GENERIC NO REF						WO#: 5592-26-15



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
45-45-CUS-9002 ^U BOTH ENGINES - DOWNLOAD THE ENGINE CONDITION TREND MONITORING (ECTM) DATA FROM THE AIRCRAFT MDC AND SEND TO ANALYST.									Service ATA:45
	DAYS		17-Mar-26					27-Jul-2026(10)	106 d
	HRS	50 (+10)	7570:23		7620:23	7630:23	17:08 (+10)		32:52
	AFL		5372						36
Disposition: CUSTOMER OPTION				REF:					
335200-701A ^U EMERGENCY LIGHTING POWER SUPPLY TEST THE EMERGENCY-LIGHTING POWER SUPPLIES PER REFERENCE. >33-00-MID-9069<									Service ATA:33
PN:501-1712-02	MOS	6	30-Jan-26		30-Jul-26		29 d	30-Jul-2026(5)	5.1
SN:80597	HRS		7544:01						59:14
	AFL		5336						72
Disposition: 05-10-25 AIRWORTHINESS				REF: SMM 33-50-00					WO#: 5592-26-15
335200-702A ^U EMERGENCY LIGHTING POWER SUPPLY TEST THE EMERGENCY-LIGHTING POWER SUPPLIES PER REFERENCE. >33-00-MID-9069<									Service ATA:33
PN:501-1712-02	MOS	6	30-Jan-26		30-Jul-26		29 d	30-Jul-2026(5)	5.1
SN:80954	HRS		7544:01						59:14
	AFL		5336						72
				REF: SMM 33-50-00					WO#: 5592-26-15
78-00-CUS-9001 ^U NO. 1 ENGINE - INSPECT/CLEAN THRUST REVERSER PDU PLUNGER									Service ATA:78
	MOS	6	30-Jan-26		30-Jul-26		29 d	30-Jul-2026(5)	5.1
	HRS		7544:01						59:14
	ENC		5343						72
Disposition: CUSTOMER CODE				REF:					WO#: 5592-26-15
78-00-CUS-9001 ^U NO. 2 ENGINE - INSPECT/CLEAN THRUST REVERSER PDU PLUNGER									Service ATA:78
	MOS	6	30-Jan-26		30-Jul-26		29 d	30-Jul-2026(5)	5.1
	HRS		7544:01						59:14
	ENC		5342						72
Disposition: CUSTOMER CODE				REF:					WO#: 5592-26-15
24-30-00-203 FUNCTIONAL TEST APU BATTERY (CAPACITY CHECK) (MRB)									Service ATA:24
PN:600-59151-11	MOS	6 (+10%/-10%)	30-Jan-26	Adj:2d	01-Aug-26	19-Aug-26	31 d (+18)	01-Aug-2026(5)	5.1
SN:090520028D84C	HRS		7544:01						59:14
	AFL		5336						72
				REF: AMM 24 32 04 720 801					WO#: 5592-26-15
38-00-MID-9086 ^U STERILIZE THE WATER SYSTEM									Service ATA:38
	MOS	6 (+10%/-10%)	06-Feb-26		06-Aug-26	24-Aug-26	36 d (+18)	06-Aug-2026(4)	4.8
	HRS		7547:05						56:10
	AFL		5340						68
				REF: SMM 38-10-00					WO#: 5592-26-15

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
21-20-00-202		OPERATIONAL TEST AVIONICS EXHAUST FAN LOW SPEED DETECTOR (MRB)							Service ATA:21
PN:604-96001-1	MOS		24-Mar-22					11-Aug-2026	51.3
SN:C04180082	HRS	1200 (+40/-40)	6430:18		7630:18	7670:18	27:03 (+40)		1172:57
	AFL		4667						741
REF: AMM 21 24 22 710 801									WO#: 5592-26-15
050013		400 HOUR CHECK							Package ATA:05
	MOS		23-Aug-24					14-Aug-2026(2)	22.3
	HRS	400 (+40/-40)	7232:48		7632:48	7672:48	29:33 (+40)		370:27
	AFL		5154						254
REF: MPD SECTION 7.1.2									WO#: 5592-26-15
351101-001A ^U		FUNCTIONAL (HYDROSTATIC) TEST UPPER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE CYLINDER							Service ATA:35
	MOS	DUE	25-Feb-22		31-Aug-26 (M)		61 d	31-Aug-2026	52.2
	HRS		6382:06						1221:09
	AFL		4638						770
Disposition: CUSTOMER CODE				REF:					
313109-001B		OPERATIONAL TEST FDR (ULB) (ULD) UNDERWATER LOCATOR BEACON (31-31-00-202)							Service ATA:31
PN:DK120/90	MOS	36 (+2m/-2m)	01-Sep-23		01-Sep-26	01-Nov-26	62 d (+61)	01-Sep-2026	34
SN:AT147598	HRS		6924:42						678:33
	AFL		4977						431
REF: AMM 31 31 07 710 801									
30-12-00-102		FUNCTIONAL TEST OF THE LOW TEMPERATURE GROUNDWING ANTI-ICE (LTGWAIS) OVERHEAT CIRCUIT(POST SB 604-30-004) (CMR**)							Service ATA:30
	MOS		20-Sep-04					16-Sep-2026	261.4
	HRS	2400	0		7654:06 (M)		50:51		7603:15
	AFL		0						5408
REF: AMM 30 12 25 720 801									WO#: 5592-26-15
271507-001B		DETAILED INSPECTION NO. 1 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-15-07-101) (CMR**)							Service ATA:27
PN:600-75142-9	MOS		19-Jul-23					06-Oct-2026	35.4
SN:HA14127	HRS	800	6867:42		7667:42		64:27		735:33
	AFL		4943						465
REF: AMM 27 15 07 220 801									WO#: 5592-26-15
271507-002B		DETAILED INSPECTION NO. 2 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-15-07-101) (CMR**)							Service ATA:27
PN:600-75142-9	MOS		19-Jul-23					06-Oct-2026	35.4
SN:HA14126	HRS	800	6867:42		7667:42		64:27		735:33
	AFL		4943						465
REF: AMM 27 15 07 220 801									WO#: 5592-26-15

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
273404-001B DETAILED INSPECTION LEFT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102) (CMR**) Service ATA:27									
PN:1018100-7	MOS		19-Jul-23					06-Oct-2026	35.4
SN:HAI3185	HRS	800	6867:42		7667:42		64:27		735:33
	AFL		4943						465
REF: AMM 27 34 04 220 801									WO#: 5592-26-15
273404-002B DETAILED INSPECTION LEFT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102) (CMR**) Service ATA:27									
PN:1018100-7	MOS		19-Jul-23					06-Oct-2026	35.4
SN:HAI4139	HRS	800	6867:42		7667:42		64:27		735:33
	AFL		4943						465
REF: AMM 27 34 04 220 801									WO#: 5592-26-15
273404-004B DETAILED INSPECTION RIGHT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102) (CMR**) Service ATA:27									
PN:1018100-7	MOS		19-Jul-23					06-Oct-2026	35.4
SN:HAI4138	HRS	800	6867:42		7667:42		64:27		735:33
	AFL		4943						465
REF: AMM 27 34 04 220 801									WO#: 5592-26-15
27-00-00-210 DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD TRAILING EDGE Service ATA:27									
	MOS	36 (+2m/-2m)	23-Oct-23		23-Oct-26	23-Dec-26	114 d (+61)	23-Oct-2026	32.3
	HRS		6963:30						639:45
	AFL		5002						406
REF: AMM 27 11 00 220 812									
32-51-04-101 DISCARD OF THE NOSEWHEEL-STEERING CONTROL POTENTIOMETER COUPLING SETSCREWS, PART NO. B0201102-2-220 (POST SB 604-32-033). (AWL*) Service ATA:32									
PN:PN	MOS	T:A/R	20-Sep-04		30-Oct-26 (M)		121 d	30-Oct-2026	261.4
SN:UNKNOWN	HRS		0						7603:15
	AFL		0						5408
Disposition: LIFE LIMIT REF: AMM 32 51 04 961 801									
SB 604-32-033 REV 01 MODIFICATION - NOSEWHEEL STEERING - REPLACEMENT OF POTENTIOMETER UNIVERSAL COUPLING (T16-6) SETSCREWS, SERVICE BULLETIN Bulletin ATA:32									
	MOS	T:36			30-Oct-26 (M)		121 d	30-Oct-2026	
	HRS								
	AFL								
Disposition: RECOMMENDED REF: BULLETINS WO#: SBS & ADS TO BE ADDRESSED									
TCCA CF-2024-12 R01 PART I REPLACEMENT OF NOSEWHEEL STEERING POTENTIOMETER UNIVERSAL COUPLING SETSCREWS AD ATA:32									
	MOS	T:36			30-Oct-26 (M)		121 d	30-Oct-2026	
	HRS	T:1400	7232:48		8632:48		1029:33		370:27
	AFL								
Disposition: MANDATORY REF: AD									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement)(EFF) - Effective C/W M-Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
38-00-MID-9085 ^U DRAIN -(WATER SYSTEM AIR FILTER)- ANY CONDENSATION BUILD-UP FROM THE AIR FILTER/REGULATOR.									
	MOS		07-May-26					11-Nov-2026(5)	1.8
	HRS	100	7590:57		7690:57		87:42		12:18
	AFL		5394						14
REF: SMM 38-10-70									
05-CUS-9001 ^U PERFORM MAINTENANCE RELEASE INSPECTION									
	MOS	14	19-Sep-25		19-Nov-26		141 d	19-Nov-2026(2)	9.4
	HRS	440	7443:24		7883:24		280:09		159:51
	AFL								
Disposition: CUSTOMER CODE REF:									
080001 ^U PERFORM AIRCRAFT WEIGHT AND BALANCE IAW CASA CAO 100.7									
	MOS	36			19-Nov-26 (M)		141 d	19-Nov-2026	
	HRS								
	AFL								
Disposition: CUSTOMER CODE REF:									
95-00-CUS-9001 ^U RENEWAL CUSTOMS CERTIFICATE									
	MOS	12	01-Dec-25		01-Dec-26		153 d	01-Dec-2026(2)	7
	HRS		7482:44						120:31
	AFL		5309						99
Disposition: CUSTOMER CODE REF:									
335101-001A FUNCTIONAL TEST FORWARD EMERGENCY POWER SUPPLY (33-50-00-201) (GRIMES PACKS)									
PN:60-1321-1	MOS	12 (+2m/-2m)	30-Jan-26	Adj:-53d	08-Dec-26	08-Feb-27	160 d (+62)	08-Dec-2026(2)	5.1
SN:9097	HRS		7544:01						59:14
	AFL		5336						72
REF: AMM 33 51 01 720 801									
FAA 2018-09-17 PARA (G) ACCOMPLISH A DETAILED OR EDDY CURRENT INSPECTION OF BOTH PILOT-SIDE RUDDER PEDAL TUBES FOR CRACKING AND CORRECTIVE ACTIONS									
	MOS		03-Feb-21					09-Dec-2026	64.9
	HRS		6159:42						1443:33
	AFL	1000	4461		5461		53		947
Disposition: MANDATORY REF: AD									
SB 604-27-037 PART A ACCOMPLISH SPECIAL CHECK / MODIFICATION - RUDDER CONTROL SYSTEM - REPLACE THE PILOT'S RUDDER PEDAL BAR ASSEMBLY OR RUDDER PEDAL ASSEMBLY, SERVICE BULLETIN SPECIAL CHECK - DVI OR EDDY CURRENT INSPECTION OF PILOT'S RUDDER PEDAL TUBES, FOR CRACKS									
	MOS		03-Feb-21					09-Dec-2026	64.9
	HRS		6159:42						1443:33
	AFL	1000	4461		5461		53		947
Disposition: RECOMMENDED REF: BULLETINS									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
TCCA CF-2017-09 PART I & II		ACCOMPLISH A DETAILED VISUAL INSPECTION (DVI) OR EDDY CURRENT INSPECTION OF BOTH PILOT-SIDE RUDDER PEDAL TUBES AND REPEAT THE INSPECTIONS (IF NO CRACKS OR DAMAGE ARE FOUND), REPLACE BOTH RUDDER BAR ASSEMBLIES (IF A CRACK IS FOUND AROUND THE AFT TAPERED HOLES) / CONTACT THE BOMBARDIER (IF ANY OTHER DAMAGE IS FOUND)							AD ATA:27
	MOS		03-Feb-21					09-Dec-2026	64.9
	HRS								
	AFL	1000	4461		5461		53		947
Disposition: MANDATORY		REF: AD							
27-00-00-211		DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE OUTBOARD TRAILING EDGE							Service ATA:27
	MOS	36 (+2m/-2m)	11-Dec-23		11-Dec-26	11-Feb-27	163 d (+62)	11-Dec-2026	30.7
	HRS		6999:30						603:45
	AFL		5022						386
		REF: AMM 27 11 00 220 813							
499100-001		APU - OIL FILTER ELEMENT							Component ATA:49
PN:365303-1	MOS		05-Sep-24	TSN:9				13-Dec-2026	21.9
SN:23-75452	HRS	500 (+30/-30)	5912	TSN:0	6412	6442	109 (+30)		391
	APUS		5912	TSN:0					323
		REF: MM 49-90-47, SIL SIL NO. APU-49, AMM 49 91 07 000 801, AMM 49 91 07 400 801							
050500		APU - 500 HOUR CHECK							Package ATA:05
	MOS		05-Sep-24					16-Dec-2026	21.9
	HRS	500 (+40/-40)	5912	Adj:2	6414	6454	111 (+40)		391
	APUS		5912						323
		REF: GENERIC NO REF							
050750		APU - 750 HOUR CHECK							Package ATA:05
	MOS		11-Sep-23					16-Dec-2026	33.7
	HRS	750 (+40/-40)	5654	Adj:10	6414	6454	111 (+40)		649
	APUS								
		REF: GENERIC NO REF							
21-30-00-203		OPERATIONAL TEST OF THE PRESSURIZATION CONTROL SYSTEM (MANUAL MODE)							Service ATA:21
	MOS		01-May-24					16-Dec-2026	26
	HRS	600 (+40/-40)	7114		7714	7754	110:45 (+40)		489:15
	AFL		5079						329
		REF: AMM 21 31 00 710 802							
53-00-MID-9088 ^U		VISUAL INSPECTION -(SATCOM RADOM FASTENERS)- OF INSERTS FOR SECURITY AND CORROSION.							Service ATA:53
	MOS		01-May-24					16-Dec-2026	26
	HRS	600	7114		7714		110:45		489:15
	AFL		5079						329
		REF:							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
53-00-MID-9094 ^U VISUAL INSPECTION -(LIGHTING DIVERter)- FOR IONIZATION DAMAGE, BREAKS, LIFTING FROM RADOME, BURNING OF END CONNECTIONS, MISSING DIVERterS.									
	MOS		01-May-24					16-Dec-2026	26
	HRS	600	7114		7714		110:45		489:15
	AFL		5079						329
REF:									
72-20-00-210 NO. 1 ENGINE - GENERAL VISUAL INSPECTION FAN SHROUD CORE MATERIAL									
	MOS		01-May-24					16-Dec-2026	26
	HRS	600 (+40/-40)	7114		(7714)7714	7754	110:45 (+40)		489:15
	ENC		5086						329
REF: AMM 72 20 00 210 805									
72-20-00-210 NO. 2 ENGINE - GENERAL VISUAL INSPECTION FAN SHROUD CORE MATERIAL									
	MOS		01-May-24					16-Dec-2026	26
	HRS	600 (+40/-40)	7114		(7714)7714	7754	110:45 (+40)		489:15
	ENC		5085						329
REF: AMM 72 20 00 210 805									
11-00-MID-9010 ^U VISUAL INSPECTION -(INTERIORS PLACARDS)- REPLACE ANY DAMAGED OR MISSING PLACARDS.									
	MOS	12 (+2m/-2m)	16-Jan-26		16-Jan-27	16-Mar-27	199 d (+59)	16-Jan-2027(2)	5.5
	HRS		7521:14						82:01
	AFL		5324						84
REF:									
31-31-00-9026 ^U FLIGHT DATA RECORDER FUNCTIONAL TEST OF RECORDED DATA OF FDR - IAW AUSTRALIAN AC21-24.									
	MOS	12	16-Jan-26		16-Jan-27		199 d	16-Jan-2027(2)	5.5
	HRS	3000	7521:14		10521:14		2917:59		82:01
	AFL		5324						84
REF:									
79-00-00-203 NO. 1 ENGINE - VISUAL CHECK OIL FILTER IMPENDING BYPASS INDICATOR									
	MOS		01-May-24					22-Jan-2027	26
	HRS	600 (+40/-40)	7114	Adj:24:12	(7738:12)7738:12	7778:12	134:57 (+40)		489:15
	ENC		5086						329
REF: AMM 79 30 10 210 801									
79-00-00-203 NO. 2 ENGINE - VISUAL CHECK OIL FILTER IMPENDING BYPASS INDICATOR									
	MOS		01-May-24					22-Jan-2027	26
	HRS	600 (+40/-40)	7114	Adj:24:12	(7738:12)7738:12	7778:12	134:57 (+40)		489:15
	ENC		5085						329
REF: AMM 79 30 10 210 801									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
25-00-MID-9250 ^U CHECK (ELT) EMERGENCY LOCATOR TRANSMITTER AND MOUNT FOR PROPER INSTALLATION AND SECURE MOUNTING (25-00-MID-9250)									
PN:453-5002	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
SN:08535	HRS		7544:01						59:14
	AFL		5336						72
REF:									
25-00-MID-9251 ^U INSPECT (ELT) EMERGENCY LOCATOR TRANSMITTER WIRING AND CONDUITS - PROPER ROUTING, SECURE MOUNTING, AND OBVIOUS DEFECTS									
PN:453-5002	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
SN:08535	HRS		7544:01						59:14
	AFL		5336						72
REF:									
25-00-MID-9252 ^U INSPECT (ELT) EMERGENCY LOCATOR TRANSMITTER BONDING AND SHIELDING - PROPER INSTALLATION/CONDITION (25-00-MID-9252)									
PN:453-5002	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
SN:08535	HRS		7544:01						59:14
	AFL		5336						72
REF:									
25-00-MID-9253 ^U INSPECT -(EMERGENCY LOCATOR TRANSMITTER)- ANTENNA, INCLUDING TRAILING ANTENNA - CONDITION, SECURE MOUNTING, AND PROPER OPERATION.									
	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
	HRS		7544:01						59:14
	AFL		5336						72
REF:									
25-00-MID-9254 ^U INSPECT -(EMERGENCY LOCATOR TRANSMITTER)- ANTENNA - SUFFICIENT SIGNAL TRANSMISSION									
	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
	HRS		7544:01						59:14
	AFL		5336						72
REF:									
25-00-MID-9255 ^U INSPECT -(EMERGENCY LOCATOR TRANSMITTER)- BATTERY - CORROSION, EXPIRATION DATE									
	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
	HRS		7544:01						59:14
	AFL		5336						72
REF:									
25-00-MID-9256 ^U INSPECT -(EMERGENCY LOCATOR TRANSMITTER)- CONTROLS AND CRASH SENSOR - PROPER OPERATION									
	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
	HRS		7544:01						59:14
	AFL		5336						72
REF:									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
262301-002D ^U CABIN FIRE EXTINGUISHER PORTABLE BOTTLE REMOVE AND WEIGH. RETURN TO AUTHORIZED SERVICE CENTER IF WEIGHT IS LESS THAN 5 LB. 13 OZ. (2.64 KG) OR IF PRESSURE GAUGE NEEDLE IS OUT OF GREEN ZONE. CHECK THAT EXTINGUISHER IS CHARGED AND UNDAMAGED, NOZZLE IS UNOBSRUCTED, AND SEAL INTACT. REPLACE ANY DAMAGED PARTS.									Service ATA:26
PN:100-9750N	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
SN:W-949019	HRS		7544:01						59:14
	AFL		5336						72
REF:									
262301-003D ^U CABIN FIRE EXTINGUISHER PORTABLE BOTTLE REMOVE AND WEIGH. RETURN TO AUTHORIZED SERVICE CENTER IF WEIGHT IS LESS THAN 5 LB. 13 OZ. (2.64 KG) OR IF PRESSURE GAUGE NEEDLE IS OUT OF GREEN ZONE. CHECK THAT EXTINGUISHER IS CHARGED AND UNDAMAGED, NOZZLE IS UNOBSRUCTED, AND SEAL INTACT. REPLACE ANY DAMAGED PARTS.									Service ATA:26
PN:100-9750N	MOS	12 (+2m/-2m)	30-Jan-26		30-Jan-27	30-Mar-27	213 d (+59)	30-Jan-2027(2)	5.1
SN:W-949023	HRS		7544:01						59:14
	AFL		5336						72
REF:									
256089-701A ^U RECERTIFY FIRST AID (MEDAIRE) KIT FIRST AID (MEDAIRE) KIT									Service ATA:25
	MOS	DUE	12-Dec-25		31-Jan-27 (M)		214 d	31-Jan-2027	6.6
	HRS		7489:53						113:22
	AFL		5304						104
Disposition: CUSTOMER CODE REF:									
30-40-00-301 DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL.NOTE: WHICHEVER INTERVAL COMES FIRST									Service ATA:30
	MOS	12 (+2m/-2m)	06-Feb-26	Adj:-6d	31-Jan-27	31-Mar-27	214 d (+59)	31-Jan-2027(2)	4.8
	HRS	600 (+40/-40)	7547:05	Adj:40	8187:05	8227:05	583:50 (+40)		56:10
	AFL		5340						68
REF: AMM 56 10 01 220 804									
050042 12 MONTH CHECK									Package ATA:05
	MOS	12 (+2m/-2m)	16-Jan-26	Adj:18d	03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027(2)	5.5
	HRS		7521:14						82:01
	AFL		5324						84
REF: GENERIC NO REF									
050044 24 MONTH CHECK									Package ATA:05
	MOS	24 (+2m/-2m)	03-Feb-25		03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027	16.9
	HRS		7357:42						245:33
	AFL		5214						194
REF: GENERIC NO REF									
237101-001A ^U FUNCTIONAL CHECK OF CVR AND CVR IMPACT SWITCH IAW CAO 100.5 APP 1 (9)									Service ATA:23
PN:2100-1025-22	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:001290711	HRS		7357:42						245:33
	AFL		5214						194
REF:									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
25-00-MID-9515 ^U VISUALLY INSPECT -(HEAT TAPE)- GENERAL CONDITION AND SECURITY. REMOVAL OF INSULATION AND WRAPPING NOT NECESSARY, UNLESS DISCREPENCY IS NOTED. INSPECTION OF TAPE IN THE GALLEY AND LAVATORY MAY BE ACCOMPLISHED USING ACCESS PANELS IN THE CABINETS.									Service ATA:25
	MOS	12 (+2m/-2m)	06-Feb-26	Adj:-3d	03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027(2)	4.8
	HRS		7547:05						56:10
	AFL		5340						68
REF:									
26-20-00-205 FUNCTIONAL TEST (WEIGHT CHECK) COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE									Service ATA:26
PN:30H673	MOS	24 (+2m/-2m)	03-Feb-25		03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027	16.9
SN:G-41049759	HRS		7357:42						245:33
	AFL		5214						194
REF: AMM 26 23 01 720 802									
28-CUS-001 ^U PERFORM FUEL TANK BIOBOR TREATMENT									Service ATA:28
	MOS	12 (+2m/-2m)	19-Feb-26	Adj:-16d	03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027(2)	4.4
	HRS		7555:45						47:30
	AFL		5350						58
REF:									
34-12-00-201 FUNCTIONAL TEST STANDBY ALTIMETER INDICATOR									Service ATA:34
PN:6420302-2	MOS	24 (+2m/-2m)	03-Feb-25		03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027	16.9
SN:K18-10021	HRS		7357:42						245:33
	AFL		5214						194
Disposition: CUSTOMER CONVENIENCE REF: AMM 34 12 01 720 801									
341201-001B RECERTIFY STANDBY ALTIMETER INDICATOR PER 14 CFR 91.411 PART 43, APP. E									Service ATA:34
PN:6420302-2	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:K18-10021	HRS		7357:42						245:33
	AFL		5214						194
Disposition: FAA REF: GENERIC NO REF									
341301-001A FUNCTIONAL TEST NO. 1 AIR DATA COMPUTER (34-13-00-102) (AWL*)									Service ATA:34
PN:822-0842-421	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:3633	HRS		7357:42						245:33
	AFL		5214						194
Disposition: RVSM REF: AMM 34 13 00 720 809									
341301-001B ^U RECERTIFY NO. 1 AIR DATA COMPUTER PER FAR 91.411									Service ATA:34
PN:822-0842-421	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:3633	HRS		7357:42						245:33
	AFL		5214						194
REF:									



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
341301-002A FUNCTIONAL TEST NO. 2 AIR DATA COMPUTER (34-13-00-102) (AWL *)									
PN:822-0842-421	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:106CT	HRS		7357:42						245:33
	AFL		5214						194
Disposition: RVSM REF: AMM 34 13 00 720 809									
341301-002B ^U RECERTIFY NO. 2 AIR DATA COMPUTER PER FAR 91.411									
PN:822-0842-421	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:106CT	HRS		7357:42						245:33
	AFL		5214						194
REF:									
345401-001A ^U RECERTIFY NO. 1 ATC TRANSPONDER NO. 1 PER FAR 91.413									
PN:622-9210-501	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:4G4Y5G	HRS		7357:42						245:33
	AFL		5214						194
REF:									
345401-002A ^U RECERTIFY NO. 2 ATC TRANSPONDER NO. 2 PER FAR 91.413									
PN:622-9210-501	MOS	24	03-Feb-25		03-Feb-27		217 d	03-Feb-2027	16.9
SN:4G4Y60	HRS		7357:42						245:33
	AFL		5214						194
REF:									
38-00-MID-9091 ^U REPLACE WATER SYSTEM AIR FILTER CARTRIDGE									
	MOS	12 (+2m/-2m)	06-Feb-26	Adj:-3d	03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027(2)	4.8
	HRS		7547:05						56:10
	AFL		5340						68
REF:									
53-ZL-00-228 GENERAL VISUAL INSPECTION AFT EQUIPMENT COMPARTMENT - INTERNAL									
	MOS	12 (+2m/-2m)	06-Feb-26	Adj:-3d	03-Feb-27	03-Apr-27	217 d (+59)	03-Feb-2027(2)	4.8
	HRS		7547:05						56:10
	AFL		5340						68
REF: SPM 20-70-00-210-801, AMM 53 30 01 210 806									
28-11-CUS-9001 ^U LUBRICATE WING FUEL CAPS O-RINGS - (FUEL LUBE OR DOW CORNING DC4)									
	MOS	12 (+2m/-2m)	11-Feb-26		11-Feb-27	11-Apr-27	225 d (+59)	11-Feb-2027(2)	4.7
	HRS		7549:54						53:21
	AFL		5344						64
Disposition: CUSTOMER CODE REF:									



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
761113-001A			FUNCTIONAL TEST NO. 1 THROTTLE CONTROL GEARBOX OF THE ENGINE THROTTLE CONTROL GEARBOX(76-11-00-101) (CMR**)						Service ATA:76
PN:2100140-007	MOS		22-Oct-20					18-Feb-2027	68.3
SN:2852	HRS	1600	6156:18		7756:18		153:03		1446:57
	AFL		4459						949
REF: AMM 76 11 13 720 802									WO#: 5592-26-15
25-11-00-201			OPERATIONAL TEST OF THE INERTIAL REEL CONTROL AND INERTIAL REEL						Service ATA:25
	MOS	36 (+2m/-2m)	22-Feb-24		22-Feb-27	22-Apr-27	236 d (+59)	22-Feb-2027	28.3
	HRS								
	AFL		5050						358
REF: AMM 25 11 04 710 801									
25-11-00-202			GENERAL VISUAL INSPECTION OF THE PILOT/COPILOT SEAT RESTRAINTS						Service ATA:25
	MOS	36 (+2m/-2m)	22-Feb-24		22-Feb-27	22-Apr-27	236 d (+59)	22-Feb-2027	28.3
	HRS								
	AFL		5050						358
REF: AMM 25 11 01 210 801									
35-00-00-204			OPERATIONAL TEST CREW OXYGEN MASK						Service ATA:35
	MOS	36 (+2m/-2m)	22-Feb-24		22-Feb-27	22-Apr-27	236 d (+59)	22-Feb-2027	28.3
	HRS								
	AFL		5050						358
REF: AMM 35 11 07 710 801									
35-00-MID-9153 ^U			EXAMINE AND TEST -(PASSENGER OXYGEN SYSTEM - FLOW RATE)- PER REFERENCE.						Service ATA:35
	MOS	36	22-Feb-24		22-Feb-27		236 d	22-Feb-2027	28.3
	HRS								
	AFL		5050						358
REF: SMM 35-20-00									
72-20-00-207			NO. 1 ENGINE - DETAILED INSPECTION OF THE MASTER CHIP DETECTOR FOR PARTICLE AND CHIP INDICATION						Service ATA:72
	MOS		30-Jan-26					22-Feb-2027(2)	5.1
	HRS	200	7544:01	Adj:15:05	(7759:06)7759:06		155:51		59:14
	ENC		5343						72
REF: AMM 79 21 13 220 801									
72-20-00-207			NO. 2 ENGINE - DETAILED INSPECTION OF THE MASTER CHIP DETECTOR FOR PARTICLE AND CHIP INDICATION						Service ATA:72
	MOS		30-Jan-26					22-Feb-2027(2)	5.1
	HRS	200	7544:01	Adj:15:05	(7759:06)7759:06		155:51		59:14
	ENC		5342						72
REF: AMM 79 21 13 220 801									



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
24-01-00-101 DISCARD OF THE EXTENSION AND RETRACTION RELAYS (K1CE) (AWL*)									
PN:PN	MOS	T:24	EFF		25-Feb-27 *		239 d	25-Feb-2027	261.4
SN:UNKNOWN	HRS	T:800	EFF		8172:28 *		569:13		7603:15
	AFL								5408
Disposition: LIFE LIMIT REF: AMM 24 01 00 961 801									
24-01-00-101 DISCARD OF THE EXTENSION AND RETRACTION RELAYS (K2CE) (AWL*)									
PN:PN	MOS	T:24	EFF		25-Feb-27 *		239 d	25-Feb-2027	261.4
SN:UNKNOWN	HRS	T:800	EFF		8172:28 *		569:13		7603:15
	AFL								5408
Disposition: LIFE LIMIT REF: AMM 24 01 00 961 801									
24-01-00-101 DISCARD OF THE EXTENSION AND RETRACTION RELAYS (K3CE) (AWL*)									
PN:PN	MOS	T:24	EFF		25-Feb-27 *		239 d	25-Feb-2027	261.4
SN:UNKNOWN	HRS	T:800	EFF		8172:28 *		569:13		7603:15
	AFL								5408
Disposition: LIFE LIMIT REF: AMM 24 01 00 961 801									
24-01-00-101 DISCARD OF THE EXTENSION AND RETRACTION RELAYS (K4CE) (AWL*)									
PN:PN	MOS	T:24	EFF		25-Feb-27 *		239 d	25-Feb-2027	261.4
SN:UNKNOWN	HRS	T:800	EFF		8172:28 *		569:13		7603:15
	AFL								5408
Disposition: LIFE LIMIT REF: AMM 24 01 00 961 801									
35-00-00-210 RESTORATION LOWER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE REGULATOR (MRB)									
PN:895-25015	MOS	DUE	25-Feb-22		25-Feb-27 (M)		239 d	25-Feb-2027	52.2
SN:ALT282-36064	HRS		6382:06						1221:09
	AFL		4638						770
Disposition: OVERHAUL REF: AMM 35 11 01 280 801									
35-00-00-210 RESTORATION UPPER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE REGULATOR (MRB)									
PN:895-25015	MOS	O/C	25-Feb-22		25-Feb-27 (M)		239 d	25-Feb-2027	52.2
SN:C16120264	HRS		6382:06						1221:09
	AFL		4638						770
REF: AMM 35 11 01 280 801									
351101-002A ^U FUNCTIONAL (HYDROSTATIC) TEST LOWER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE									
PN:895-25015	MOS	DUE	25-Feb-22		25-Feb-27 (M)		239 d	25-Feb-2027	52.2
SN:ALT282-36064	HRS		6382:06						1221:09
	AFL		4638						770
REF:									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
27-50-00-104 FUNCTIONAL TEST OF THE FLAP EXTENSION AND RETRACTION (FLAP HALF-SPEED TEST). (CMR*)									
	MOS		19-Mar-25					26-Mar-2027	15.4
	HRS	400	7379:54		7779:54		176:39		223:21
	AFL		5227						181
Disposition: CMR* REF: AMM 27 50 00 720 801									
FAA 2023-17-06 FLIGHT CONTROLS - UNCOMMANDED FLAP EXTENSION AD ATA:27									
	MOS		01-Aug-25					14-Apr-2027	11
	HRS	400	7392:36		7792:36		189:21		210:39
	AFL		5239						169
Disposition: MANDATORY REF: AD									
SB 604-27-040 SPECIAL CHECK - FLAPS - INTRODUCTION OF INITIAL AND REPEAT OPERATIONAL TEST OF THE FLAPS TO VERIFY THE RETRACTION / EXTENSION TIME, SERVICE BULLETIN Bulletin ATA:27									
	MOS		01-Aug-25					14-Apr-2027	11
	HRS	400	7392:36		7792:36		189:21		210:39
	AFL		5239						169
Disposition: RECOMMENDED REF: BULLETINS									
27-14-01-101 FUNCTIONAL TEST AILERON POWER CONTROL UNITS (PCUS) (CMR**) Service ATA:27									
	MOS		19-Dec-23					03-May-2027	30.4
	HRS	800	7005		7805		201:45		598:15
	AFL		5026						382
REF: AMM 27 14 01 720 801									
57-60-00-101 DETAILED INSPECTION OF THE AILERON (AWL*) Service ATA:57									
	MOS		06-Apr-16					06-Jun-2027	122.8
	HRS		5115:48						2487:27
	AFL	1867	3653		5520		112		1755
Disposition: AIRWORTHINESS REF: AMM 57 60 01 220 801									
52-20-00-202 FUNCTIONAL TEST EXIT-PULL SIGN Service ATA:52									
	MOS	36 (+2m/-2m)	11-Jun-24		11-Jun-27	11-Aug-27	345 d (+61)	11-Jun-2027	24.7
	HRS		7154:18						448:57
	AFL		5100						308
REF: AMM 52 21 07 720 801									
28-10-00-213 VISUAL CHECK VENT/DISTRIBUTION SHROUD DRAINS BLOCKAGE/LEAKAGE Service ATA:28									
	MOS		23-Aug-24					14-Jun-2027	22.3
	HRS	600 (+40/-40)	7232:48		7832:48	7872:48	229:33 (+40)		370:27
	AFL		5154						254
REF: AMM 28 00 00 210 801									



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
31-41-00-201	OPERATIONAL TEST OF THE DATA CONCENTRATOR UNIT (DCU) (MASTER WARNING/MASTER CAUTION SIGNALS)								Service ATA:31
	MOS		23-Aug-24					14-Jun-2027	22.3
	HRS	600 (+40/-40)	7232:48		7832:48	7872:48	229:33 (+40)		370:27
	AFL		5154						254
REF: AMM 31 41 04 710 802									
273504-001A	FUNCTIONAL TEST NO. 1 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY LINEARITY (27-35-04-101) (CMR*)								Service ATA:27
PN:600-59154-3	MOS		28-Jan-26					27-Jun-2027	5.1
SN:GST05056	HRS	300	7542:34	Adj:-1:28	7841:06		237:51		60:41
	AFL		5335						73
REF: AMM 27 35 04 720 801									
273504-002A	FUNCTIONAL TEST NO. 2 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY LINEARITY (27-35-04-101) (CMR*)								Service ATA:27
PN:600-59154-3	MOS		28-Jan-26					27-Jun-2027	5.1
SN:54686	HRS	300	7542:34	Adj:-1:28	7841:06		237:51		60:41
	AFL		5335						73
REF: AMM 27 35 04 720 801									
27-13-04-101	OPERATIONAL TEST ROLL DISCONNECT SYSTEM (CMR*)								Service ATA:27
	MOS		01-Feb-24					29-Jun-2027	29
	HRS	800	7042:18		7842:18		239:03		560:57
	AFL		5042						366
REF: AMM 27 13 04 710 801									
27-32-00-101	OPERATIONAL TEST ELEVATOR DISCONNECT SYSTEM (CMR*)								Service ATA:27
	MOS		01-Feb-24					29-Jun-2027	29
	HRS	800	7042:18		7842:18		239:03		560:57
	AFL		5042						366
REF: AMM 27 32 00 710 801									
FAA 2003-22-12 PARA (N) LEFT	SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - LEFT ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES (AMOC AND TASK 27-35-04-101*)								AD ATA:27
	MOS		28-Jan-26					29-Jun-2027	5.1
	HRS	300	7542:34		7842:34		239:19		60:41
	AFL		5335						73
REF: AD									
FAA 2003-22-12 PARA (N) RIGHT	SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - RIGHT ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES (AMOC AND TASK 27-35-04-101*)								AD ATA:27
	MOS		28-Jan-26					29-Jun-2027	5.1
	HRS	300	7542:34		7842:34		239:19		60:41
	AFL		5335						73
REF: AD									



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
256093-701B ^U RENEW LIFE RAFT 406 MHZ ELT - REGISTRATION									
PN:913FAUL-3KO-1-100	MOS	24	14-Jul-25		14-Jul-27		378 d	14-Jul-2027	11.6
SN:9ULU-10004	HRS								
	AFL								
Disposition: CUSTOMER CODE				REF:					
27-21-00-101 FUNCTIONAL TEST RUDDER BACKLASH (CMR**)									
	MOS		19-Feb-24					22-Jul-2027	28.4
	HRS	800	7057:18		7857:18		254:03		545:57
	AFL		5048						360
REF: AMM 27 21 00 720 805									
27-33-01-101 FUNCTIONAL TEST ELEVATOR BACKLASH (CMR*)									
	MOS		19-Feb-24					22-Jul-2027	28.4
	HRS	800	7057:18		7857:18		254:03		545:57
	AFL		5048						360
REF: AMM 27 31 00 720 805									
237121-001B OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR)UNDERWATER LOCATING DEVICE (ULD)									
PN:DK120/90	MOS	36 (+2m/-2m)	05-Aug-24		05-Aug-27	05-Oct-27	400 d (+61)	05-Aug-2027	22.9
SN:AT207797	HRS		7199:12						404:03
	AFL		5127						281
REF: AMM 23 71 03 710 801									
262301-001C ^U COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE RETURN TO AUTHORIZED SERVICE CENTER FOR TEARDOWN (COMPLETE MAINTENANCE).									
PN:30H673	MOS	72	12-Aug-21		12-Aug-27		407 d	12-Aug-2027	58.6
SN:G-41049759	HRS		6235:24						1367:51
	AFL		4536						872
Disposition: CUSTOMER CODE				REF:					
53-10-00-107 DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD - VERTICAL STIFFENER BL22 (AWL*)									
	MOS		20-Sep-04					21-Aug-2027	261.4
	HRS		0						7603:15
	AFL	T:5545	0		5545		137		5408
Disposition: AIRWORTHINESS				REF: AMM 53 10 01 220 820					
27-41-00-101 OPERATIONAL TEST (BITE) OF THE HORIZONTAL-STABILIZER TRIM-CONTROL SYSTEM (HSTCS) (CMR**)									
	MOS		29-Aug-24					27-Aug-2027	22.1
	HRS	640	7241:06		7881:06		277:51		362:09
	AFL		5158						250
REF: AMM 27 41 00 740 801									



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
57-ZL-00-228	GENERAL VISUAL INSPECTION WING TRAILING EDGE - INTERNAL LH								Service ATA:57
	MOS	36 (+2m/-2m)	29-Aug-24		29-Aug-27	29-Oct-27	424 d (+61)	29-Aug-2027	22.1
	HRS		7241:06						362:09
	AFL		5158						250
REF: SPM 20-70-00-210-801, AMM 57 50 01 210 802									
72-00-CUS-9001 ^U	NO. 1 ENGINE - COMPRESSOR WASH								Service ATA:72
	MOS		19-Dec-25					15-Sep-2027	6.4
	HRS	400	7493:37		(7893:37)7893:37		290:22		109:38
	ENC		5314						101
Disposition: CUSTOMER CODE REF: WO#: 5592-26-15									
72-00-CUS-9001 ^U	NO. 2 ENGINE - COMPRESSOR WASH								Service ATA:72
	MOS		19-Dec-25					15-Sep-2027	6.4
	HRS	400	7493:37		(7893:37)7893:37		290:22		109:38
	ENC		5313						101
Disposition: CUSTOMER CODE REF: WO#: 5592-26-15									
23-00-MID-9051 ^U	PERFORM -(AUTO THROTTLE THRUST REVERSER DIODES)- DIODE TEST PROCEDURE PER BOMBARDIER AEROSPACE SUP. MAINT. MANUAL, TE-22305001-SMM (REV. A) SECTION 23-30-00.								Service ATA:23
	MOS		18-Apr-24					16-Oct-2027	26.5
	HRS	800	7114		7914		310:45		489:15
	AFL		5079						329
REF:									
71-61-00-202	LUBRICATION OF THE BALLSCREW ACTUATORS SUPPORT BUSHINGS								Service ATA:71
	MOS		01-May-24					16-Oct-2027	26
	HRS	800 (+40/-40)	7114		7914	7954	310:45 (+40)		489:15
	AFL		5079						329
REF: AMM 12 20 04 640 827									
78-30-00-202	LUBRICATION OF THE THRUST-REVERSER BALLSCREW ACTUATORS								Service ATA:78
	MOS		01-May-24					16-Oct-2027	26
	HRS	800 (+40/-40)	7114		7914	7954	310:45 (+40)		489:15
	AFL		5079						329
REF: AMM 12 20 04 640 824									
79-00-00-204	NO. 1 ENGINE - DISCARD OIL FILTER ENGINE OIL FILTER ELEMENT								Service ATA:79
PN:PN	MOS		24-Jan-22					08-Nov-2027	53.3
SN:UNKNOWN	HRS	1600 (+40/-40)	6329:30		(7929:30)7929:30	7969:30	326:15 (+40)		1273:45
	ENC		4615						800
Disposition: LIFE LIMIT REF: AMM 79 21 07 960 801									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
79-00-00-204 NO. 2 ENGINE - DISCARD OIL FILTER ENGINE OIL FILTER ELEMENT									
PN:PN	MOS		24-Jan-22					08-Nov-2027	53.3
SN:UNKNOWN	HRS	1600 (+40/-40)	6329:30		(7929:30)7929:30	7969:30	326:15 (+40)		1273:45
	ENC		4614						800
Disposition: LIFE LIMIT REF: AMM 79 21 07 960 801									
24-23-00-101 OPERATIONAL TEST AIR DRIVEN GENERATOR (ADG). (CMR*)									
	MOS	24	18-Nov-25	Adj:-2d	16-Nov-27		503 d	16-Nov-2027	7.5
	HRS	1600	7471:54		9071:54		1468:39		131:21
	AFL		5297						111
REF: AMM 24 23 01 710 801									
273113-001A FUNCTIONAL TEST OF THE NO. 1 PITCH FEEL SIMULATOR. (CMR**)									
PN:600-92300-61	MOS		03-Feb-22					02-Dec-2027	52.9
SN:10540	HRS	1600	6345:18		7945:18		342:03		1257:57
	AFL		4621						787
REF: AMM 27 31 13 720 801									
273113-002A FUNCTIONAL TEST OF THE NO. 2 PITCH FEEL SIMULATOR. (CMR**)									
PN:600-92300-61	MOS		03-Feb-22					02-Dec-2027	52.9
SN:10539	HRS	1600	6345:18		7945:18		342:03		1257:57
	AFL		4621						787
REF: AMM 27 31 13 720 801									
73-10-00-201 NO. 1 ENGINE - DISCARD FUEL FILTER ELEMENT									
	MOS		24-Jan-22					05-Dec-2027	53.3
	HRS	1600 (+40/-40)	6329:30	Adj:17:48	(7947:18)7947:18	7987:18	344:03 (+40)		1273:45
	ENC		4615						800
Disposition: LIFE LIMIT REF: AMM 73 11 07 960 801									
73-10-00-201 NO. 2 ENGINE - DISCARD FUEL FILTER ELEMENT									
	MOS		24-Jan-22					05-Dec-2027	53.3
	HRS	1600 (+40/-40)	6329:30	Adj:17:48	(7947:18)7947:18	7987:18	344:03 (+40)		1273:45
	ENC		4614						800
Disposition: LIFE LIMIT REF: AMM 73 11 07 960 801									
21-24-34-301 OPERATIONAL TEST DATA CONCENTRATOR UNIT (DCU) FAN									
	MOS		24-Jan-22					06-Dec-2027	53.3
	HRS	1600 (+40/-40)	6329:30	Adj:18:30	7948	7988	344:45 (+40)		1273:45
	AFL		4608						800
REF: AMM 21 24 34 710 801									



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
24-21-00-101 FUNCTIONAL TEST GCU OVERVOLTAGE PROTECTION CIRCUITS (CMR*)									
	MOS		14-Feb-22					16-Dec-2027	52.6
	HRS	1600	6361:24	Adj:-7:18	7954:06		350:51		1241:51
	AFL		4631						777
REF: AMM 24 20 00 720 801									
050015 600 HOUR CHECK									
	MOS		03-Feb-25					21-Dec-2027	16.9
	HRS	600 (+40/-40)	7357:42		7957:42	7997:42	354:27 (+40)		245:33
	AFL		5214						194
REF: MPD SECTION 7.1.2									
259500-701E ^U REPLACE DEFIBRILLATOR INFANT PAD									
PN:M5072A	MOS	DUE	16-Dec-25		27-Dec-27 (M)		544 d	27-Dec-2027	6.5
SN:C062725-13	HRS								
	AFL								
Disposition: DISCARD REF:									
25-60-00-202 DISCARD OF THE EMERGENCY LOCATOR TRANSMITTER UNIT (ELT) BATTERY									
PN:452-0133	MOS	DUE	19-Jul-23		01-Jan-28 (M)		549 d	01-Jan-2028	35.4
SN:398554-032	HRS		6867:42						735:33
	AFL		4943						465
Disposition: LIFE LIMIT REF: AMM 25 62 01 960 801									
259500-701D ^U REPLACE DEFIBRILLATOR PADS									
PN:M5071A	MOS	DUE	16-Dec-25	TSN:0	01-Jan-28 (M)		549 d	01-Jan-2028	6.5
SN:C070125-02	HRS		7490:09	TSN:0					113:06
	AFL		5305	TSN:0					103
REF:									
21-51-00-301 CLEAN WATER SEPARATOR									
	MOS		25-Jun-24					12-Jan-2028	24.2
	HRS	800 (+40/-40)	7162:12	Adj:9:48	7972	8012	368:45 (+40)		441:03
	AFL		5105						303
REF: AMM 21 51 13 160 801									
56-10-00-102 DETAILED INSPECTION OF THE SIDE WINDOW - 4 BUSHING HOLES (AWL*)									
	MOS		14-Nov-25					23-Jan-2028	7.6
	HRS		7471:06						132:09
	AFL	300	5296		5596		188		112
Disposition: AIRWORTHINESS REF: AMM 56 10 01 220 802									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
30-22-00-101 OPERATIONAL TEST OF THE COWL ANTI-ICE FAILURE INDICATION (POST SB 604-30-004) (CMR*)									
	MOS		01-Apr-25					24-Jan-2028	15
	HRS	600	7379:54		7979:54		376:39		223:21
	AFL		5227						181
REF: AMM 30 22 00 710 801									
050046 36 MONTH CHECK									
	MOS	36 (+2m/-2m)	03-Feb-25		03-Feb-28	03-Apr-28	582 d (+60)	03-Feb-2028	16.9
	HRS		7357:42						245:33
	AFL		5214						194
REF: GENERIC NO REF									
291152-001A OPERATIONAL TEST NO. 1 HYDRAULIC SHUTOFF VALVE (29-11-52-201)									
PN:601R75151-7	MOS		10-Jul-25					09-Feb-2028	11.7
SN:B42601	HRS	600 (+40/-40)	7390:48		7990:48	8030:48	387:33 (+40)		212:27
	AFL		5236						172
Disposition: MRB REF: AMM 29 11 52 710 801									
291152-002A OPERATIONAL TEST NO. 2 HYDRAULIC SHUTOFF VALVE (29-11-52-201)									
PN:601R75151-7	MOS		10-Jul-25					09-Feb-2028	11.7
SN:DC18993	HRS	600 (+40/-40)	7390:48		7990:48	8030:48	387:33 (+40)		212:27
	AFL		5236						172
Disposition: MRB REF: AMM 29 11 52 710 801									
34-54-00-201 OPERATIONAL TEST ATC TRANSPONDER SELECT SWITCH									
	MOS	24 (+2m/-2m)	30-Jan-26	Adj:23d	22-Feb-28	22-Apr-28	601 d (+60)	22-Feb-2028	5.1
	HRS		7544:01						59:14
	AFL		5336						72
Disposition: CUSTOMER OPERATIONS REQUIREMENT REF: AMM 34 54 00 710 801									
SB 604-34-072 PART A ACCOMPLISH SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-102, SERVICE BULLETIN INSPECT THE PART NUMBER OF THE GPS CURRENTLY INSTALLED									
	MOS	T:DUE	EFF		31-Mar-28 * (M)		639 d	31-Mar-2028	
	HRS								
	AFL								
Disposition: RECOMMENDED REF: BULLETINS									
SB 604-34-072 PART B ACCOMPLISH SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-102, SERVICE BULLETIN REPLACE THE GPS UNITS, PART NO. 822-2189-101 WITH PART NO. 822-2189-102									
	MOS	T:DUE	EFF		31-Mar-28 * (M)		639 d	31-Mar-2028	
	HRS								
	AFL								
Disposition: RECOMMENDED REF: BULLETINS									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement)(EFF) - Effective C/W M-Manual Due (EBT) - Estimated Base Time



Due List Report

Model: CL-604 Serial: 5592 RegNo: VH-L2B HRS: 7603:15 AFL: 5408 As Of: 30-Jun-2026 Operator: EXECUJET AUSTRALIA PTY LTD

Report Date: 02-Jul-2026

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
32-40-00-201 FUNCTIONAL TEST BRAKE ACCUMULATORS									
	MOS		23-Aug-24					13-Apr-2028	22.3
	HRS	800 (+40/-40)	7232:48		8032:48	8072:48	429:33 (+40)		370:27
	AFL		5154						254
REF: AMM 32 43 07 720 801									WO#: 5592-26-15
32-40-00-204 LUBRICATION MLG BRAKE CONTROL VALVE ASSEMBLY									
	MOS		23-Aug-24					13-Apr-2028	22.3
	HRS	800 (+40/-40)	7232:48		8032:48	8072:48	429:33 (+40)		370:27
	AFL		5154						254
REF: AMM 12 20 04 640 825									WO#: 5592-26-15
256093-702B ^U RENEW LIFE RAFT 406 MHZ ELT - REGISTRATION									
PN:913FAUL-7K0-1-100	MOS	24	07-May-26		07-May-28		676 d	07-May-2028	1.8
SN:9UL-00352	HRS		7590:57						12:18
	AFL		5394						14
Disposition: CUSTOMER OPTION REF:									
FAA 2023-06-04 PASSENGER OXYGEN MASK DISPENSING UNITS (MDUS) LANYARDS TOO LONG TO MEET THE PROPER LENGTH SPECIFICATIONS AD ATA:35									
	MOS	T:60	EFF		18-May-28 *		687 d	18-May-2028	
	HRS								
	AFL								
Disposition: MANDATORY REF: AD									
FAA 2022-09-01 PARA (H) ACCOMPLISH APPLICABLE ACTIONS INCLUDING AN INSPECTION FOR DISCREPANCIES OF THE POTABLE WATER-LINE RIBBON HEATER AND REPAIR OF ANY DISCREPANT POTABLE WATER-LINE RIBBON HEATERS USING A METHOD APPROVED (FOR AIRPLANES WITH A SERIAL NUMBER THAT IS NOT LISTED IN SECTION 1.A OF THE SERVICE INFORMATION SPECIFIED IN FIGURE 1 TO PARA (G), AND FOR BOMBARDIER MODEL CL-600-1A11 AIRPLANES) AD ATA:30									
	MOS	T:72	EFF		31-May-28 *		700 d	31-May-2028	
	HRS								
	AFL								
Disposition: MANDATORY REF: AD									
256093-701A ^U LIFE RAFT RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE AND HYDROSTATIC TEST									
PN:913FAUL-3KO-1-100	MOS	36	14-Jul-25		14-Jul-28		744 d	14-Jul-2028	11.6
SN:9ULU-10004	HRS								
	AFL								
REF:									