



DueList Report

PHENOM 300

S/N 50500482 N30NB

OWNER: SOUTHERN AIR SERVICES PTY LTD

OPERATOR: SOUTHERN AIR SERVICES PTY LTD

OPERATOR: EXECUJET AUSTRALIA PTY LTD

ADDRESS: CORNER SCOTT STREET & MCMEEKIN ROAD WARRANBOOL VIC 3280

ADDRESS: CORNER SCOTT STREET & MCMEEKIN ROAD WARRANBOOL VIC 3280

ADDRESS: HANGAR 394 MASCOT NSW 2020
OFFICE: 011-61-2-9693-0800
FAX: 011-61-2-9693-0889

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: GOWTHAM THAMMISSETTY

-- (DIRECT)

EMAIL: GOWTHAM.THAMMISSETTY@CAMPSYSTEMS.COM

+1-631-588-3200 (MAIN)

WWW.CAMPSYSTEMS.COM

PROJECTED: 14 MOS. to 31-MAR-2026

AIRCRAFT	SERIAL/REGNO: 50500482/N30NB	MODEL: PHENOM 300	MANUFACTURER: EMBRAER
----------	------------------------------	-------------------	-----------------------

CERTIFICATION DATE: 26-SEP-2018

LAST ACTUALS:

PROJECTED:

939.5 A/C HRS as of 06-JAN-2025

1636.48

725 AFL as of 06-JAN-2025

1212

ENGINE NO. 1	SERIAL/PART: PCE-DG0963/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
--------------	-------------------------------------	---------------	--

INSTALLED ON: 26-SEP-2018

LAST ACTUALS:

PROJECTED:

0 ENG. HRS 0 A/C HRS

939.5 ENG. HRS as of 06-JAN-2025

1636.48

0 ENC

725 ENC as of 06-JAN-2025

1212

ENGINE NO. 2	SERIAL/PART: PCE-DG0964/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
--------------	-------------------------------------	---------------	--

INSTALLED ON: 26-SEP-2018

LAST ACTUALS:

PROJECTED:

0 ENG. HRS 0 A/C HRS

939.5 ENG. HRS as of 06-JAN-2025

1636.48

0 ENC

725 ENC as of 06-JAN-2025

1212



Insufficient Items

Operator Review and Action Required

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of: 06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

These tasks have insufficient information for calculating next due. Please provide the missing information (marked by ?) so that they can be setup properly. It is important to note that any task that has insufficient information, will not come due correctly unless the necessary information is provided by you.

PN & SN	Unit	Effective Date	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Disposition
00-CUS-001		RECERTIFY BAGGAGE WEIGH SCALE					Service ATA:00
	MOS		12 (+14d/-14d)			?	
	HRS						
	AFL						
ENTER MISSING C/W DATE _____				REF: _____			
00-CUS-002		INSTALL MARINE SAFETY SIGNAL KIT					Service ATA:00
	MOS		DUE			?	
	HRS						
	AFL						
ENTER MISSING DATE OF EXPIRATION _____, MANUAL NEXTDUE _____				REF: _____			

Name: _____ Signature: _____ Cert.#: _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
25-61-04-001		DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY							
PN:S1820606-01E	MOS	DUE			01-Jan-25 (M)		OVD		Service ATA:25
SN:NSN	HRS								
	AFL								
Disposition: LIFE LIMIT		REF: AMM 25-61-04							
SB 505-25-0044		EQUIPMENT/FURNISHINGS - LH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION, SERVICE BULLETIN							
	MOS	T:DUE			12-Sep-24 (M)		OVD		Bulletin ATA:25
	HRS								
	AFL								
Disposition: RECOMMENDED		REF: BULLETINS							
31-33-03-001		DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED)							
PN:266-E5542-00	MOS	DUE			01-Feb-25 (M)		1 d	01-Feb-2025	Service ATA:31
SN:ULB021372	HRS								
	AFL								
Disposition: LIFE LIMIT		REF: AMM 31-33-03							
24-36-01-005		FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)							
PN:7638-48P	MOS	6 (+1m/-1m)	02-Oct-24	Adj:-22d	11-Mar-25	11-Apr-25	39 d (+31)	11-Mar-2025(3)	3.9
SN:G03160036	HRS		898.5						41
	AFL		706						19
		REF: AMM 24-36-01							
24-36-01-005		FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015)							
PN:7639-34	MOS	6 (+1m/-1m)	02-Oct-24	Adj:-22d	11-Mar-25	11-Apr-25	39 d (+31)	11-Mar-2025(3)	3.9
SN:G03180635	HRS		898.5						41
	AFL		706						19
		REF: AMM 24-36-01							
35-11-02-003		DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK							
PN:MC40-011	MOS	12 (+1m/-1m)	23-Mar-24		23-Mar-25	23-Apr-25	51 d (+31)	23-Mar-2025(2)	10.3
SN:1450	HRS		853.1						86.4
	AFL		668						57
		REF: AMM 35-11-02							
35-11-02-003		DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK							
PN:MC40-011	MOS	12 (+1m/-1m)	23-Mar-24		23-Mar-25	23-Apr-25	51 d (+31)	23-Mar-2025(2)	10.3
SN:1455	HRS		853.1						86.4
	AFL		668						57
		REF: AMM 35-11-02							



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
31-31-03-001		DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							
PN:266-E5542-00	MOS	DUE			01-Apr-25 (M)		60 d	01-Apr-2025	Service ATA:31
SN:ULB023527	HRS								
	AFL								
Disposition: LIFE LIMIT		REF: AMM 31-31-03							
24-36-01-003		DISCARD AFT MAIN BATTERY							
PN:7638-48P	MOS	24 (+1m/-1m)	27-Apr-23		27-Apr-25	27-May-25	86 d (+30)	27-Apr-2025	21.1
SN:G03160036	HRS		726.7						212.8
	AFL	600 (+30/-30)	571		1171	1201	446 (+30)		154
Disposition: LIFE LIMIT		REF: AMM 24-36-01							
24-36-01-003		DISCARD FORWARD MAIN BATTERY							
PN:7639-34	MOS	24 (+1m/-1m)	27-Apr-23		27-Apr-25	27-May-25	86 d (+30)	27-Apr-2025	21.1
SN:G03180635	HRS		726.7						212.8
	AFL	600 (+30/-30)	571		1171	1201	446 (+30)		154
Disposition: LIFE LIMIT		REF: AMM 24-36-01							
72-60-01-212-801		NO. 1 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES							
	MOS							09-Jul-2025	76.2
	HRS	1200 (+100)	EFF		(1200)1200 *	1300	260.5 (+100)		939.5
	ENC								725
		REF: GENERIC NO REF							
72-60-01-212-801		NO. 2 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES							
	MOS							09-Jul-2025	76.2
	HRS	1200 (+100)	EFF		(1200)1200 *	1300	260.5 (+100)		939.5
	ENC								725
		REF: GENERIC NO REF							
SB PW500-72-30555		NO. 1 ENGINE - INSPECTION OF HYDRAULIC PUMP DRIVE GEARSHAFT SPLINES, SERVICE BULLETIN							
	MOS							09-Jul-2025	76.2
	HRS	T:1200 (+50/-50)	EFF		(1200)1200 *	1250	260.5 (+50)		939.5
	ENC								
Disposition: CATEGORY 3		REF: BULLETINS							
SB PW500-72-30555		NO. 2 ENGINE - INSPECTION OF HYDRAULIC PUMP DRIVE GEARSHAFT SPLINES, SERVICE BULLETIN							
	MOS							09-Jul-2025	76.2
	HRS	T:1200 (+50/-50)	EFF		(1200)1200 *	1250	260.5 (+50)		939.5
	ENC								
Disposition: CATEGORY 3		REF: BULLETINS							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
05-30-01		800 FH MAINTENANCE PACKAGE							Package	ATA:05
	MOS		12-Sep-21					28-Jul-2025	40.6	
	HRS	800 (+30/-30)	432		1232	1262	292.5 (+30)		507.5	
	AFL		377						348	
REF: SMR 05-30-01										
25-62-01-001		VISUAL CHECK #1 FIRST AID KIT							Service	ATA:25
PN:019708-0005L	MOS	DUE	08-Feb-24		01-Aug-25 (M)		182 d	01-Aug-2025	11.7	
SN:8012549374	HRS									
	AFL									
REF: AMM 25-62-01										
05-30-80		12 MO MAINTENANCE PACKAGE							Package	ATA:05
	MOS	12 (+1m/-1m)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS		898.5						41	
	AFL		706						19	
REF: SMR 05-30-80										
051254		NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package	ATA:05
	MOS	12 (+30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS	800 (+10%)	898.5		(1698.5)1698.5	1778.5	759 (+80)		41	
	ENC		706						19	
REF: MM 05-20-00										
051254		NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package	ATA:05
	MOS	12 (+30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS	800 (+10%)	898.5		(1698.5)1698.5	1778.5	759 (+80)		41	
	ENC		706						19	
REF: MM 05-20-00										
22-11-00-001		FUNCTIONAL CHECK AILERON GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service	ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
SN:1GK022959	HRS		898.5						41	
	AFL		706						19	
Disposition: AIRWORTHINESS REF: AMM 22-11-00										
22-11-00-001		FUNCTIONAL CHECK ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service	ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
SN:1GK020069	HRS		898.5						41	
	AFL		706						19	
Disposition: AIRWORTHINESS REF: AMM 22-11-00										

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
22-11-00-001 FUNCTIONAL CHECK RUDDER GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO									
PN:011-01904-00	MOS	12 (+30d/-30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9
SN:1GK022957	HRS		898.5						41
	AFL		706						19
Disposition: AIRWORTHINESS REF: AMM 22-11-00									
22-11-00-001 FUNCTIONAL CHECK TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT GSA 80 HIGH SPEED AUTOPILOT SERVO									
PN:011-01904-00	MOS	12 (+30d/-30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9
SN:1GK022978	HRS		898.5						41
	AFL		706						19
Disposition: AIRWORTHINESS REF: AMM 22-11-00									
25-61-00-001 OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM									
PN:S1821502-02	MOS	12	02-Oct-24	Adj:-31d	01-Sep-25		213 d	01-Sep-2025	3.9
SN:LX1100734208	HRS		898.5						41
	AFL		706						19
REF: AMM 25-61-00									
25-61-00-002 GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER									
PN:S1821502-02	MOS	12	02-Oct-24	Adj:-31d	01-Sep-25		213 d	01-Sep-2025	3.9
SN:LX1100734208	HRS		898.5						41
	AFL		706						19
REF: AMM 25-61-00									
26-24-01-001 WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER									
PN:RT-A1200	MOS	12	02-Oct-24	Adj:-31d	01-Sep-25		213 d	01-Sep-2025	3.9
SN:A25951509	HRS		898.5						41
	AFL		706						19
REF: AMM 26-24-01									
26-24-01-001 WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER									
PN:RT-A1200	MOS	12	02-Oct-24	Adj:-31d	01-Sep-25		213 d	01-Sep-2025	3.9
SN:A25951426	HRS		898.5						41
	AFL		706						19
REF: AMM 26-24-01									
32-11-00-003 LUBRICATION OF MAIN LANDING GEAR									
	MOS	12 (+1m/-1m)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9
	HRS		898.5						41
	AFL	650 (+30/-30)	706		1356	1386	631 (+30)		19
REF: AMM 12-21-00									



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
32-11-03-004		SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER							Service	ATA:32
	MOS	12 (+1m/-1m)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS		898.5						41	
	AFL	650 (+30/-30)	706		1356	1386	631 (+30)		19	
REF: AMM 12-14-02										
32-21-00-003		LUBRICATION OF NOSE LANDING GEAR							Service	ATA:32
	MOS	12 (+1m/-1m)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS		898.5						41	
	AFL	650 (+30/-30)	706		1356	1386	631 (+30)		19	
REF: AMM 12-21-00										
32-21-05-004		SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER							Service	ATA:32
	MOS	12 (+1m/-1m)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS		898.5						41	
	AFL	650 (+30/-30)	706		1356	1386	631 (+30)		19	
REF: AMM 12-14-03										
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service	ATA:33
PN:7450LS-00	MOS	12	02-Oct-24	Adj:-31d	01-Sep-25		213 d	01-Sep-2025	3.9	
SN:005308	HRS		898.5						41	
	AFL		706						19	
REF: AMM 33-52-01										
35-11-00-001		OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX							Service	ATA:35
	MOS	12 (+30d/-30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS	800 (+30/-30)	898.5		1698.5	1728.5	759 (+30)		41	
	AFL		706						19	
Disposition: AIRWORTHINESS										
REF: AMM 35-11-02										
73-10-05-212-801		NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service	ATA:73
	MOS	12 (+30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS		898.5						41	
	ENC		706						19	
REF: MM 73-10-05										
73-10-05-212-801		NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service	ATA:73
	MOS	12 (+30d)	02-Oct-24	Adj:-31d	01-Sep-25	01-Oct-25	213 d (+30)	01-Sep-2025	3.9	
	HRS		898.5						41	
	ENC		706						19	
REF: MM 73-10-05										



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
25-21-04-001		RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) - NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY							Service	ATA:25
PN:PN	MOS	84	26-Sep-18		26-Sep-25		238 d	26-Sep-2025	76.2	
SN:UNKNOWN	HRS		0						939.5	
	AFL		0						725	
REF: AMM 25-21-04										
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service	ATA:33
PN:7450LS-00	MOS	12	02-Oct-24		02-Oct-25		244 d	02-Oct-2025	3.9	
SN:005446	HRS		898.5						41	
	AFL		706						19	
REF: AMM 33-52-01										
71-00-00-760-823		NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service	ATA:71
	MOS	12 (+30d)	02-Oct-24		02-Oct-25	01-Nov-25	244 d (+30)	02-Oct-2025	3.9	
	HRS	630 (+10%)	898.5		(1528.5)1528.5	1591.5	589 (+63)		41	
	ENC		706						19	
REF: MM 71-00-00										
71-00-00-760-823		NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service	ATA:71
	MOS	12 (+30d)	02-Oct-24		02-Oct-25	01-Nov-25	244 d (+30)	02-Oct-2025	3.9	
	HRS	630 (+10%)	898.5		(1528.5)1528.5	1591.5	589 (+63)		41	
	ENC		706						19	
REF: MM 71-00-00										
72-00-02-810-801		NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service	ATA:71
	MOS	12	02-Oct-24		02-Oct-25		244 d	02-Oct-2025	3.9	
	HRS	630	898.5		(1528.5)1528.5		589		41	
	ENC		706						19	
REF: MM 72-00-02										
72-00-02-810-801		NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service	ATA:71
	MOS	12	02-Oct-24		02-Oct-25		244 d	02-Oct-2025	3.9	
	HRS	630	898.5		(1528.5)1528.5		589		41	
	ENC		706						19	
REF: MM 72-00-02										
SB PW500-72-30571		NO. 1 ENGINE - INSPECTION OF GAS GENERATOR TO TURBINE SUPPORT CASE BOLTS, SERVICE BULLETIN							Bulletin	ATA:72
	MOS							15-Oct-2025		
	HRS									
	ENC	T:400	EFF		(1020)1020 *		295			

Disposition: CATEGORY 3

REF: BULLETINS



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
SB PW500-72-30571		NO. 2 ENGINE - INSPECTION OF GAS GENERATOR TO TURBINE SUPPORT CASE BOLTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS							15-Oct-2025		
	HRS									
	ENC	T:400	EFF		(1020)1020 *		295			
Disposition: CATEGORY 3		REF: BULLETINS								
22-11-03-001 ^S		DISCARD OF AILERON CLUTCH RETAINING BOLT AND WASHER
							Service	ATA:22
	MOS	36 (+1m/-1m)	26-Sep-18		29-Oct-25 (M)	29-Nov-25	271 d (+31)	29-Oct-2025	76.2	
		REF: AMM 22-11-03								
FAA 2023-22-11		REPLACEMENT OF THE AILERON AUTOPILOT SERVO MOUNT CLUTCH RETAINING BOLT AND WASHER							AD	ATA:22
	MOS	36	29-Oct-22		29-Oct-25		271 d	29-Oct-2025	27.1	
	HRS		650.2						289.3	
	AFL									
Disposition: MANDATORY		REF: AD								
73-10-05-960-801		NO. 1 ENGINE - DISCARD THE FUEL FILTER							Service	ATA:73
PN:3052624-01	MOS		22-Sep-22					03-Dec-2025	28.3	
SN:UNKNOWN	HRS	800 (+10%)	641.8		(1441.8)1441.8	1521.8	502.3 (+80)		297.7	
	ENC		519						206	
		REF: MM 73-10-05								
73-10-05-960-801		NO. 2 ENGINE - DISCARD THE FUEL FILTER							Service	ATA:73
PN:3052624-01	MOS		22-Sep-22					03-Dec-2025	28.3	
SN:UNKNOWN	HRS	800 (+10%)	641.8		(1441.8)1441.8	1521.8	502.3 (+80)		297.7	
	ENC		519						206	
		REF: MM 73-10-05								
79-20-01-960-801		NO. 1 ENGINE - DISCARD THE OIL FILTER							Service	ATA:79
PN:3052590-01	MOS		22-Sep-22					03-Dec-2025	28.3	
SN:UNKNOWN	HRS	800 (+10%)	641.8		(1441.8)1441.8	1521.8	502.3 (+80)		297.7	
	ENC		519						206	
Disposition: DISCARD		REF: MM 79-20-01								
79-20-01-960-801		NO. 2 ENGINE - DISCARD THE OIL FILTER							Service	ATA:79
PN:3052590-01	MOS		22-Sep-22					03-Dec-2025	28.3	
SN:UNKNOWN	HRS	800 (+10%)	641.8		(1441.8)1441.8	1521.8	502.3 (+80)		297.7	
	ENC		519						206	
Disposition: DISCARD		REF: MM 79-20-01								
24-31-01-001		NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017							Service	ATA:24
PN:400SG180Q	MOS		01-Sep-23					15-Feb-2026	17	
SN:S02036XL	HRS	800 (+30/-30)	762.9		1562.9	1592.9	623.4 (+30)		176.6	
	AFL		611						114	
		REF: AMM 24-31-01								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500482 RegNo: N30NB HRS: 939.5 AFL: 725 As Of:
06-Jan-2025 Operator: SOUTHERN AIR SERVICES PTY LTD

Report Date: 31-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
24-31-01-001		NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017								Service ATA:24
PN:400SG180Q-4	MOS		01-Sep-23					15-Feb-2026	17	
SN:S01031XL	HRS	800 (+30/-30)	762.9		1562.9	1592.9	623.4 (+30)		176.6	
	AFL		611						114	
REF: AMM 24-31-01										
28-21-07-001		OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM								Service ATA:28
	MOS		01-Sep-23					15-Feb-2026	17	
	HRS	800 (+30/-30)	762.9		1562.9	1592.9	623.4 (+30)		176.6	
	AFL		611						114	
Disposition: AIRWORTHINESS REF: AMM 28-21-07										
28-21-07-001		OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM								Service ATA:28
	MOS		01-Sep-23					15-Feb-2026	17	
	HRS	800 (+30/-30)	762.9		1562.9	1592.9	623.4 (+30)		176.6	
	AFL		611						114	
Disposition: AIRWORTHINESS REF: AMM 28-21-07										
32-43-11-001		OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE								Service ATA:32
	MOS		01-Sep-23					15-Feb-2026	17	
	HRS	800 (+30/-30)	762.9		1562.9	1592.9	623.4 (+30)		176.6	
	AFL		611						114	
Disposition: AIRWORTHINESS REF: AMM 32-43-11										
05-30-10		1600 FH MAINTENANCE PACKAGE								Package ATA:05
	MOS		26-Sep-18					10-Mar-2026	76.2	
	HRS	1600 (+30/-30)	0		1600	1630	660.5 (+30)		939.5	
	AFL		0						725	
REF: SMR 05-30-10										